



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary
www.dep.wv.gov

Thursday, February 17, 2022
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / New Drill

ANTERO RESOURCES CORPORATION
1615 WYNKOOP STREET

DENVER, CO 80202

Re: Permit cancellation for TRAINER UNIT 2H
47-017-06869-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-017-06869-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 2/17/2022 .

If there are any questions, please feel free to contact me at (304) 926- 0450

A handwritten signature in blue ink, appearing to read 'James A. Martin', is written over a faint, larger version of the signature.

James A. Martin
Chief

Operator's Well Number: TRAINER UNIT 2H
Farm Name: PHILLIP N. HILL, ET AL
U.S. WELL NUMBER: 47-017-06869-00-00
Horizontal 6A New Drill
Date Cancelled: 2/17/2022

Promoting a healthy environment.

02/25/2022

INSPECTORS PERMIT SUMMARY FORM

PAGE 1

GPS YES ___ NO X

Cancel Never Drilled

DATE STARTED/LOCATION: [] API #: [] WELL NO. Trainer Unit 24

DRILLING COMMENCED: [] OPERATOR: Antero Resources Corporation

TD DATE: [] DEPTH: [] FARM: Phillip N. Hill ETAL

WATER DEPTHS [] COAL DEPTHS []

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:

A. CONSTRUCTION YES ___ NO ___ (2 PTS) B. DRILLING YES ___ NO ___ (2 PTS)

2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES ___ NO ___ (4 PTS) (4 PTS) 0

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES ___ NO ___ (4 PTS) (4 PTS) 0

4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? (4 PTS) 0

4. CONSTRUCTION:

WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1 ___ 2 ___ 3 ___ 4 ___ (PTS) B. CROSS DRAINS 1 ___ 2 ___ 3 ___ 4 ___ 5 ___ (PTS)

C. CULVERTS 1 ___ 2 ___ 3 ___ 4 ___ 5 ___ (PTS) D. CREEK CROSSINGS 1 ___ 2 ___ 3 ___ (PTS)

E. DIVERSION DITCHES 1 ___ 2 ___ 3 ___ (PTS) F. BARRIERS 1 ___ 2 ___ 3 ___ (PTS)

G. TEMPORARY SEEDING YES ___ NO ___ (10 PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) 0

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES ___ NO ___ (2 PTS) (2 PTS) 0

6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES ___ NO ___ (9 PTS) (9 PTS) 0

7. RECLAMATION:

A. ROADWAY 1 ___ 2 ___ 3 ___ (PTS) B. LOCATION 1 ___ 2 ___ 3 ___ (PTS)

C. PITS 1 ___ 2 ___ 3 ___ (PTS) D. PIPELINES 1 ___ 2 ___ 3 ___ (PTS)

E. TANK DIKES 1 ___ 2 ___ 3 ___ (PTS) F. API INSTALLED YES ___ NO ___ (3 PTS)

G. ADEQUATE SEEDING MATERIALS 1 ___ 2 ___ 3 ___ (PTS)

H. WAS SEED BED ADEQUATE 1 ___ 2 ___ 3 ___ (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) 0

8. WAS RECLAMATION COMPLETED WITHIN:

A. CONVENTIONAL:

6 MTHS OF TD ___ 6 PTS ONLY; 4 MTHS OF TD ___ 12 PTS ONLY; 2 MTHS OF TD ___ 19 PTS ONLY.

B. HORIZONTAL:

3 YRS OF PAD COMPLETION ___ 19 PTS ONLY; 4 YRS OF PAD COMPLETION ___ 16 PTS ONLY; 5 YRS OF PAD COMPLETION ___ 13 PTS ONLY

MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) 0

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: 0

2/16/2022
DATE RELEASED

[Signature]
INSPECTOR

Cancel Never Drilled

02/18/2022