



New Location   
 Drill Deeper   
 Abandonment

Company Point Pleasant Oil & Gas Co.  
 Address Hamlin W. Va.  
 Farm Katherine B. & Joseph Lunsford  
 Tract 1 Acres 163 Lease No. 2  
 Well (Farm) No. 1 Serial No. 1  
 Elevation (Spirit Level) 60'  
 Quadrangle Pt. Pleasant-SC  
 County Mason District Lewis  
 Engineer S.V. Haworth  
 Engineer's Registration No. 224  
 File No. \_\_\_\_\_ Drawing No. \_\_\_\_\_  
 Date 8/29/40 Scale 1" = 50'

STATE OF WEST VIRGINIA  
 DEPARTMENT OF MINES  
 OIL AND GAS DIVISION  
 CHARLESTON

WELL LOCATION MAP  
 FILE NO. MASON-26-P

+ Denotes location of well on United States Topographic Maps, scale 1 to 62,500, latitude and longitude lines being represented by border lines as shown.  
 - Denotes one inch spaces on border line of original tracing.

0.09 S.  
 0.09 W.  
 8 NE (H-3)

Deep Well

WEST VIRGINIA DEPARTMENT OF MINES  
OIL & GAS DIVISION  
W E L L R E C O R D

Permit No. Mas-26			Dry Hole
Company	Point Pleasant Oil & Gas Co.		Casing & Tubing
Address	8114 Sycamore Street, Hamlin, W. Va.	10	21'4"
Farm	Katherine B. Lunsford Acres--	8 1/2	278'
Well No	1 Elev. 601	6 5/8	1503'
Surface	--	5 3/16	1862'
Mineral	Katherine B. Lunsford, Point Pleasant, W. Va.		
Commenced	Sept. 2, 1940		
Completed	Mar. 12, 1941		
Shot	Mar 15, 1941	Depth 2635-3415'	
Salt Water	469-504'		

*Lewis dit-  
Norm C.*

Clay	0	16	
Sand	16	40	
Clay - Blue	50	48	
Slate - Gray	48	52	
Slate	52	92	
Red Rock	92	103	
Black Slate	103	109	
Gray Slate	109	128	
Sand	128	136	
Red Rock	136	230	
Slate	230	260	
Red Rock	260	275	
Slate	275	318	
Red Rock	318	350	
Slate	350	419	
Red Rock	419	469	
Salt Sand	469	504	
Slate	504	570	
Sand	570	700	
White Slate	700	764	
Slate & Shells	764	917	
Sand	917	999	
Sand-Maxon	<del>999</del>	1068	
Slate & Shells	1068	1114	
Sand	1114	1192	
Big Lime	1192	1290	
Slate & Shells	1290	1642	
Hard Shell	1642	1658	
White Slate	1658	1753	
Berea Sand	1753	1771	- 3-5" B/W water
Slate & Shells	1771	1861	
Hard Shell	1861	1870	
Slate & Shells	1870	2010	
Hard Shell	2010	2023	
Gray Slate	2023	2289	Light show of gas in shale before shot
Hard Shell	2289	2303	
Gray Slate	2303	2345	
Hard Shell	2345	2357	
Gray Slate	2357	2600	
Gray Shale	2600	2650	
Gray Slate	2650	2680	
Brown Shale	2680	2698	
Gray Slate	2698	2735	
Brown Shale	2735	2818	
Hard Shell	2818	2840	
White Slate	2840	2905	
Brown Shale	2905	3045	
Light Shale & Slate	3045	3330	
Brown Shale	3330	3415	Shot 2635-3415'
Corniferous Lime		3415	
TOTAL DEPTH		3415	

3415  
601  

---

2814

1753  
601  

---

1152

Not enough gas to gauge in 1" after cleaning out.