WR-35 Rev (9-11)

## State of West Virginia Department of Environmental Protection Office of Oil and Gas Well Operator's Report of Well Work

DATE:	2012-03-13	
API#:	4705901949	

	Quadrangle: Mallory  County: Mingo, WV  J. 37 Min. 40 Sec.			
District: Unknown				
Latitude: 37.64377 Feet South of Deg				
Longitude -81.84613 Feet West of West Dep	g. <u>81</u> Min	., <u>50</u> Sec	• .	
FORD 1 (b) O				
Company: EQT Production Company		1		
Address: EQT Plaza, Suite 1700	Casing & Tubing	Used in drilling	Left in well	Cement fill up Cu. Ft.
625 Liberty Avenue, Pittsburgh, PA 15222	13 3/8	43	43	- up 04/14
Agent: Cecil Ray	9 5/8	1,014	1,014	472
Inspector: Barry Stollings	7	3,120	3,120	718.25
Date Permit Issued: 2008-07-15	4 1/2	10,339	10,339	
Date Well Work Commenced: 2009-09-24				
Date Well Work Completed:				
Verbal Plugging:				
Date Permission granted on:			Office of	Oll & Gas
Rotary Cable Rig V				1 4 0040
Total Vertical Depth (ft):			WAR	4 2012
Total Measured Depth (ft): 10,358			1452 150	and the same of the same
Fresh Water Depth (ft.):		gor/4	AAA FAA	<del>dal Protec</del> t
Salt Water Depth (ft.):		Sami .	Whylling:	areas s seems
Is coal being mined in area (N/Y)?				
Coal Depths (ft.):				
Void(s) encountered (N/Y) Depth(s)	·			

I certify under penalty of law that I have personally examined and am familiar with the information submitted on this document and all the attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information I believe that the information is true, accurate, and complete.

Signature

2012-03-13 Date

Were core samples taken? Yes	No Were cutting	gs caught during drilling? Yes	No
Were Electrical, Mechanical or Geophy	sical logs recorded on this well? If yes, p	blease list	
		, , , , , , , , , , , , , , , , , , ,	
FRACTURING OR STIMULATING DETAILED GEOLOGICAL RECO	PUT THE FOLLOWING: 1). DIG, PHYSICAL CHANGE, ETC. 2). THE TOPS AND BOTTOMY OF THE TOPS AND BOTTOMY ELLBORE FROM SURFACE TO TO	IE WELL LOG WHICH IS A S MS OF ALL FORMATIONS,	SYSTEMATIC
Perforated Intervals, Fracturing, or Stin	rulating:		
This well was not completed and	I therefore has no perforation det	ails.	
Plug Back Details Including Plug Type	and Depth(s): N/A		
and the Name of the Association of Marie Property and the Association of the Association			-T-1-04-tra
Formations Encountered: Surface:	Top Depth	/ Bottom	<u>Depth</u>
And the second of the second o			. · · · · · · · · · · · · · · · · · · ·
		ESS 1072 (20) x	
			etho h v v v
to White Hilliam Profession Commission Commi			
		MAR I	4 2012
1	THE CONTRACTOR AND THE STOP CONTRACTOR AND ADDRESS OF THE CONTRACTOR ADDRESS	WV Depa	strent of
4		Environment	al Protectic
, and the second	Manual de la companya		,
		<u> </u>	
	U WANTED THE THE THE WANTED THE	***************************************	· · · · · · · · · · · · · · · · · · ·
	940/94/1994/94/94/94/94/94/94/94/94/94/94/94/94/		