

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE MADE IN TRIPLICATE, one copy mailed to the Division, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

CONSOL PENNSYLVANIA COAL CO, LLC.
Coal Operator or Owner
1525 PLEASANT GROVE RD. CLAYSVILLE, PA 15323
1000 CONSOL ENERGY DRIVE CANONSBURG, PA 15317
Address

CONSOL PENNSYLVANIA COAL CO, LLC.
Coal Operator or Owner
1525 PLEASANT GROVE RD. CLAYSVILLE, PA 15323
1000 CONSOL ENERGY DRIVE CANONSBURG, PA 15317
Address

VIOLETTA MATTHEWS
Lease or Property Owner
2421 4th STREET MOUNDSVILLE, WV 26041
Address

CONSOL PENNSYLVANIA COAL CO, LLC.
Name of Well Operator
192 CRABAPPLE ROAD WIND RIDGE, PA 15380
Complete Address

CAMERON, WV 7.5'
Well Location

CAMERON
District

MARSHALL
County

5045
Well No.

MATTHEWS, VIOLETTA
Farm

5045
Well No.

MATTHEWS, VIOLETTA
Farm

MATTHEWS, VIOLETTA
Farm

MATTHEWS, VIOLETTA
Farm

STATE INSPECTOR SUPERVISING PLUGGING _____

AFFIDAVIT

STATE OF WEST VIRGINIA,
County of MONONGALIA ss:

RUSSELL SMALLWOOD and KEVIN WRIGHT being first duly sworn according to law depose and say that they are experienced in the work of plugging and filling oil and gas wells and were employed by Consol Pennsylvania Coal Company, LLC. Well Operator, and participated in the work of plugging and filling the above well, that said work was commenced on the 9th day of July, 2012 and that the well was plugged in the following manner:

Sand or Zone Record Formation	Filling Material	Casing/Tubing Size	Casing Pulled	Casing Left In
Cleaned 12 1/4" hole from the surface to top of 8 5/8" casing at 384'. Reduced hole to 7 7/8" at 384'. Cleaned 7 7/8" hole from 384' to 1452'. Tagged solid plug at 1452'. Removed 594' of 8 5/8" casing from 384' to 978' with extreme difficulty due to casing being ripped and parted. Due the 8 5/8" casing being cemented in the hole, the casing could not be removed from 978' to 1542'. Left an unknown amount of 8 5/8" casing in hole from 978' to an unknown depth. Cut remaining 8 5/8" casing at the following depths: 1377', 1282', 1184', 1173', 1123', 1028', 1023' and 990'. Cleaned 12 1/4" hole from 384' to 968'. Reduced hole to 9 7/8" at 968'. Cleaned 9 7/8" hole from 968' to top of remaining 8 5/8" casing at 978'. Reduced hole to 7 7/8" at 978'. Cleaned 7 7/8" hole from 978' to 1452'. Cleaned 9 7/8" hole through Pittsburgh Coal (968' to 973'). Left 20' of 16" conductor pipe in hole from 20' to surface.	16" Conductor 8 5/8" Casing	0' 594'	20' Unknown	
Cemented hole from 1452' back to surface as follows: From 1452' to 1173' with Expandable Cement. From 1173' to 868' with 165 sacks of Thixotropic Cement with green dye. From 868' to surface with Expandable Cement. A total of 720 sacks of cement were used fill the hole from 1452' to surface, (555 sacks of Expanadable Cement - 165 sacks of Thixotropic Cement). Cement did circulate at the surface.				
Coal Seams	Description of Monument			
<u>Pittsburgh</u>	<u>(968' - 973')</u>	77" of 7" casing w/ company name, well number, permit number and date cemented stated on 7" casing. Well marker will be attached to the cement plug at ground level.		

... and that the work of plugging and filling said well was completed on the 30th day of July, 2012

And further deponents saith not.

Russell Smallwood
Russell Smallwood


Kevin S. Wright
Kevin S. Wright

Sworn to and subscribed before me this 13th day of August 2012

Jacqueline R. Shier
Notary Public

My commission expires:

March 18, 2020



Permit No. 47-51-01516-P
Well No. 5045

08/31/2012