

METT MOY Farm Bob Price (Observed) API #47: -061- 0701- Red (Revised 3-81) Date June 23, 1982 OFFICE OF OIL AND GAS - DEPARTMENT OF MINES OIL AND GAS WELL PERMIT APPLICATION WELL TYPE: Oil / Gas X / Abandoned (If "Gas", Production\_\_/ Underground storage\_\_/ Deep\_\_/ Shallow Elevation: 1369.67 Watershed: Jakes Rum
District: Clay County: Monongalia LOCATION: Quadrangle: Blacksville 7.5' WELL OPERATOR Consolidation Coal Company DESIGNATED AGENT Roger E. Duckworth Address P. O. Box 1314 P. O. Box 1314 Morgantown, WV 26507-1314 Morgantown, WV 26507-1314 OIL AND GAS ROYALTY OWNER N/A COAL OPERATOR Consolidation Coal Company
Address P. O. Box 1314 Address\_\_\_\_ Morgantown, WV 26507-1314 Acreage -COAL OWNER(S) WITH DECLARATION ON RECORD: SURFACE OWNER Bob Prince NAME Same Address Pentress, WV Address -Acreage 78.98 NAME -Address FIELD SALE (LF MADE) TO: DDA DbA Address. COAL LESSEE WITH DEGLARATION ON RECORD: METO Address OIL AND GAS INSPECTOR TO BE NOTIFIED: William Blosser NAME RECEIVED Address Colfax, WV Telephone 363-9105 JUN 3 0 1922 OIL AND GAS DIVISION WY DEPARTMENT OF MINES The undersigned well operator is entitled to operate for oil or gas purposes at the above location under a deed \_\_/\_ lease\_\_\_/ other contract X \_\_/\_ dated \_\_\_\_\_, 19\_\_\_\_ to the undersigned well operator from \_Bob Price (If said deed, lease, or other contract has been recorded:) Recorded on \_\_\_\_\_\_, 19\_\_\_\_, in the office of the Clerk of County Commission of County, West Virginia, in \_\_\_\_\_Book at page \_\_\_\_\_. A permit is requested as follows: PROPOSED WORK: Drill / Drill Deeper / Redrill X / Fracture or stimulate\_\_\_\_ Plug off old formation X / Perforate new formation / Other physical change in well (specify) --planned as shown on the work order on the reverse side hereof. The above named coal operator, coal owner(s), and coal lessee are hereby notified that a objection they wish to make or are required to make by Code \$22-4-3 must be filed with the Department of Mines within fifteen (15) days after receipt of this Application by the De

Copies of this Permit Application and the enclosed plat and reclamation plan have been nailed by registered mail or delivered by hand to the above named coal operator, coal own er(s), and coal lessees on or before the day of the mailing or delivery of this Applicati to the Department of Mines at Charleston, West Virginia. LEASE SUBMIT COPIES OF ALL GEOPHYSICAL LOGS DIRECTLY TO: CONSOLIDATION COAL COMPANY Well Operator JEST VIRGINIA OIL AND GAS

ONSERVATION COMMISSION 613 WASHINGTON ST., E. BLANKET BOND HARLESTON, WV 25311

lts: Project Engineer

## PROPOSED WORK ORDER

## THIS IS AN ESTIMATE ONLY: ACTUAL INFORMATION MUST BE SUBMITTED ON FORM IV-35 UPON COMPLETION

			· KNOWN)_		Daybro	ok Develop	ment Co.		
			Address_		Daybroo				•
				<del></del>		•			
Approxii Approxii	ed dept mate wa mate co	th of co iter str pal seam	TION ompleted ata dept depths: n this a	hs: 93	Fresh	,	et. Rota feet;	ry/ Cab salt,	ole tools/ feet.
CASING AND				٠, .				.:	•
CASING OR TUBING TYPE	1		CIFICATI Weight	ONS		FOOTAGE	INTERVALS	CEMENT FILL	7 PACKERS -
	Size	Grade-	per ft	New	Used	hot nell	- Left in	UP OR SACKS Cubic ft.	. Nekeks =
Conductor Fresh water	-1- :	= =	-	·				Cubic Tt.	Kinds
Coal	T				-				1
Intermed	1	SE	E EXHIBIT	NO.					Sizes
Production Tubing	1								l l
iners							:		Depths set
_									Perforations:
							· ·		Top - Botto
-	. 1				-	:			al and four
Form 1 822-4- requir 822-4- posed A sepa where sought	tion 1 V-9, " 12b an ed by 8a fra well. rate Fo fractus	2, or i Reclama d Regula Code \$2 m the or  orm IV- ring or s noted	n lieu t tion Pla ation 23 2-4-12a, mer of c 2 shall n stimular	hereon" ap , (iv and any w  not be ting	of the plical ) unle (v) ij ater u	other se le-to th ess previ applica ell or d ired for	curity ale reclama ously paid ble, the welling was fracturing	lowed by Code tion required to the same consent required thin 200 fee	e well, the fe ired by Code et of the pro-
ALL PROVIS  ARTICLE 4.0  APPROVED  IF CPERATIC  BY  The following	OF THE W FOR TE LNS HAVE	VA. COD drilling NOT CC.	rfel	WITH CI	HAPTER : S HEREBY SHALL EX 12-83	22, , (PIRE			rewith.

-IV-38 (Affidavit of Plugging)

## STATE OF WEST VIRGINIA DEPARTMENT OF MINES

OIL AND GAS WELLS DIVISION .

RECEIVE

JAN 6 - 1983

## AFFIDAVIT OF PLUGGING AND FILLING WELDLAND GAS DIVISION WYDEPARTMENT OF MINES

Consolidation Coal Company	Conc	Olidation C	<b>a</b>	•	
COAL OPERATOR OR OWNER	Cons	olidation Coal		· .	
P. O. Box 1314, Morgantown, WV 26507-1314	. P. O	Box 1314. More		•	
Same		COMPLETE	ADDRESS	_26507_	
COAL OPERATOR OR OWNER	Dece	mber 10		19.8	
	Clay	WELL AND L	LOCATION		
Bob Price				Dist	
LEASE OR PROPERTY OWNER	Monor	ngalia	ty fire	Cou	
	Well. N	Consol 4819			
ADDRESS	wett. 14				
		Bob Price		Fa	
STATE INSPECTOR SUPERVISING PLUGGING	Willi	am Blosser, Col	far ww	. 4	
			IUX, WV		
STATE OF WEST VIRGINIA.	VIT			•	
		•	•	•	
County of Monongaria					
Larry Yost	d D	avid Yost			
being first duly sworn according to law depose an	d say the	t they are experi	enced in the	· work	
plugging and filling oil and gas wells and were employeel operator, and participated in the work of plugge	wad her	Consolidation	C1 C	- WOLA	
well operator, and participated in the work of plugg	ing and	filing the character	Coal Compar	ıy	
was commenced on the 2 day of Sentember		ming me spoke	well, that s	aid wo	
was commenced on the 2 day of September and filled in the following manner:	,	$19_{82}$ , and that	the well was	ı blugg	
AND OR ZONE RECORD FILLING MATERIAL					
PORMATION		PLUGS USED	e	SING	
Cleaned wellbore to 1508'. Ran coal protection		SIZE & KIND	PULLED	G 5	
String as follows: 2.7/98 + 1:	13	10" or 12"	H		
2 3/8" tubing from 1490' to	10661		914' to	<b>5</b> 53'	
12" casing from 10k6! to sympage Ist 1	1066',	2 3/8" tubing	1490' to	1066'	
$4\frac{1}{2}$ " casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066'	1066',		914' to 1490' to 1066' to	1066'	
4½" casing from 1056' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066'	1066',	2 3/8" tubing	1490' to	1066'	
4½" casing from 1056' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac por Poz Mix followed by 300 sacks of expanding	1066',	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water	1066',	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water	1066',	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water	1066', t	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with value.	1066', t	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with value.	1066', t	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with value.	1066', t	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water	1066', t	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water	1066', t	2 3/8" tubing	1490' to	1066'	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water	1066', t	2 3/8" tubing	1490' to	1066'	
A½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.	1066',	2 3/8" tubing 4½" casing	1490' to	1066' surfac	
A½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL SEAMS  Bottom Pittsburgh at 914'	1066', t	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½	1490' to 1066' to	1066' surfac	
A½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL STAMS  Bottom Pittsburgh at 914'	1066', t	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta	1490' to 1066' to	1066' surfac	
Bottom Pittsburgh at 914'	1066', t	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta	1490' to 1066' to	1066' surface	
4½" casing from 10 66' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL STAMS  Bottom Pittsburgh at 914'	1066',	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta  061-0701-R-P	1490' to 1066' to	1066' surface	
4½" casing from 10 66' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL STAMS  Bottom Pittsburgh at 914'	1066',	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta  061-0701-R-P	NOF MONUMENTO O. D. casting: Conso	1066' surface	
directly casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL STAMS  Bottom Pittsburgh at 914'  The state of plugging and filling said well september  22	1066',	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta  061-0701-R-P	1490' to 1066' to	1066' surface	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL SEAMS  Bottom Pittsburgh at 914'  and that the work of plugging and filling said well September  19	1066',	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta  061-0701-R-P	NOF MONUMENTO O. D. casting: Conso	1066' surface	
directly casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL STAMS  Bottom Pittsburgh at 914'  The state of plugging and filling said well september  22	1066',	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta  061-0701-R-P	NOF MONUMENTO O. D. casting: Conso	1066' surface	
And further deponents saith not.  Latch down a 1054', float valve at 1060' and swedge at 1066'  Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water.  Let set, bailed dry.  COAL SEAMS  Bottom Pittsburgh at 914'  And further deponents saith not.	1066',	2 3/8" tubing  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta  061-0701-R-P	NOF MONUMENTO O. D. casting: Conso	1066' surface	
4½" casing from 1066' to surface. Latch down a 1054', float valve at 1060' and swedge at 1066' Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water. Let set, bailed dry.  COAL SEAMS  Bottom Pittsburgh at 914'  And that the work of plugging and filling said well September  19	1066',	2 3/8" tubing  4½" casing  Five feet of 4½  with plaque star  061-0701-R-P  inpleted on the	N OF MONUMENT O. D. casting: Conso	surface surfac	
And further deponents saith not.  Latch down a 1054', float valve at 1060' and swedge at 1066'  Circulated cement to surface as follows: 700 sac of Poz Mix followed by 300 sacks of expanding cement. Displaced cement to 1054' with water.  Let set, bailed dry.  COAL SEAMS  Bottom Pittsburgh at 914'  And further deponents saith not.	was con	DESCRIPTION  4½" casing  DESCRIPTION  Five feet of 4½  with plaque sta  061-0701-R-P  Inpleted on the  Lagranter	N OF MONUMENT O. D. casting: Conso	ing 1 4819	