



RECEIVED

DEC 27 1982

OIL AND GAS DIVISION WY DEPARTMENT OF MINES

Oil and Gas Division

OIL AND GAS WELL PERMIT APPLICATION

TO THE DEPARTMENT OF MINES,		
Charleston, W. Va.	DATE December 27, 1982	
Surface Owner Wheeling Dollar Savings & Trust	Company Eastern Associated C	oal Corp.
Address 1315 Market St., Wheeling, WV 26003	Address Rt. 1, Fairview, WV	26570
Mineral Owner Wheeling Dollar Savings & Trust	Farm Denny Tennant	Acres 149
Address 1315 Market St., Wheeling, WV 26003	Location (waters) Miracle Run	
Coal Owner Wheeling Dollar Savings & Trust	Well No. EACC-F2-294	Elevation 1087.58
Address 1315 Market St., Wheeling, WV 26003	District Battelle	County Monongali
Coal Operator Eastern Associated Coal Corp. Rt. 1, Fairview, WV 26570	Quadrangle Wadestown - 7½'	*
THIS PERMIT MUST BE POSTED AT THE WELL SITE.		
ALL PROVISIONS REINO NA		
ALL PROVISIONS BEING IN ACCORDANCE WITH CHAPTER	22,	
ARTICLE 4 OF THE MINNS HERE	SPECTOR \	•
- redribling ERMIT SHALL FO	BE NOTIFIED William Blosse:	
ADI	RESS Box 1028, Colfax, WV	26566
THOUSE PROPERTY.	ONE (304) 363-9105	
GENTLEMEN:		
The undersigned well operator is entitled to drill upon the a	bove named farm or tract of land for o	il and see having for
title thereto, (or as the case may be) under grant or lease dat		
made to		
19 in County, Book	Page	_ 42, 01
NEW WELLDRILL DEEPERXX		
XXXX OIL AND GAS WELL ORIGINALLY DRILLED I		E OR STIMULATE
THE PROPERTY OF THE PROPERTY O	SEFORE JUNE 5, 1969.	
The enclosed plat was prepared by a registered engineer or have been notified as of the above date.	licensed land surveyor and all coal own	ers and/or operators
The above named coal owners and/or operator are hereby no to make by Section 3 of the Code, must be received by, or filed	tified that any objection they wish to n d with the Department of Mines within	nake, or are required ten (10) days. *
Copies of this notice and the enclosed plat were mailed by reor coal owners at their above shown respective address	dav	
same day with the mailing or delivery of this copy to the Depar		hefore or on the
	tment of Mines at Charleston, West Virg	hefore or on the
	tment of Mines at Charleston, West Virgery truly young,	hefore or on the
PLEASE SUBMIT COPIES OF ALL	ery truly you're	hefore or on the
PLEASE SUBMIT COPIES OF ALL	ign Name) South Veite	before, or on the ginia.
PLEASE SUBMIT COPIES OF ALL GEOPHYSICAL LOGS DIRECTLY TO: (Some of the second of the s	ign Name) Shu A. Veite	before, or on the rinia.
PLEASE SUBMIT COPIES OF ALL GEOPHYSICAL LOGS DIRECTLY TO: (S) WEST VIRGINIA GEOLOGICAL AND ECONOMIC SURVEY Address	ign Name) Well Operator Northern Division Com Eastern Associated Co Rt. 1, Box Street	before, or on the rinia.
PLEASE SUBMIT COPIES OF ALL GEOPHYSICAL LOGS DIRECTLY TO: (So WEST VIRGINIA GEOLOGICAL AND ECONOMIC SURVEY Address P. O. BOX 879	wen Operator Northern Division Com Eastern Associated Co Rt. 1, Box 1447 Fairview	before, or on the rinia.
PLEASE SUBMIT COPIES OF ALL GEOPHYSICAL LOGS DIRECTLY TO: (So WEST VIRGINIA GEOLOGICAL AND ECONOMIC SURVEY P. O. BOX 879 Well Operator	well Operator Northern Division Con Eastern Associated Co Rt. 1, Box 144	before, or on the rinia.

*SECTION 3 . . . If no objections are filed or found by the Department of mines, within said period of ten days from the receipt of notice and plat by the department of mines, to said proposed location, the department shall forthwith issue to the well operator a permit reciting the filing of such plat, that no objections have been made by the coal operators or found thereto by the department and that the same is approved and the well operator authorized to proceed.

BLANKET BOND

Juni. e. 1

ACTUAL INFORMATION WILL BE SUBMITTED ON OG-10 UPON COMPLETION

PROPOSED WORK ORDER	TO XXX RE-DRILL	DEEPEN FI	RACTURE STIMULATE
DRILLING CONTRACTOR:		RESPONSIBLE AGENT	
NAME Chisler Brothers			
ADDRESS Pentres	s, WV	ADDRESS Rt. 1, Fa	irview, WV 26570
TELEPHONE (304) 8	79-5511	TELEPHONE (304) 4	49-1911, ext. 250
ESTIMATED DEPTH OF COM	PLETED WELL 3027 Ft.		CABLE TOOLS. XXX
PROPOSED GEOLOGICAL FO	RMATION: GORDON		
TYPE OF WELL: OI	L_XXXX GAS	COMB STORAGE	DISPOSAT
×			ODOTHER
			ob other
TENTATIVE CASING PROGR.	AM: (See Affidavit of	Plugging Form OG-8)	
CASING AND TUBING			
SIZE	USED FOR DRILLING	LITTIN	CIMINETHILLP
20 - 16			OR SACKS CUBIC 11
13 - 10	,	I	
9 - 5/8			
8 - 5/8			
7			
5 1/2			
4 ½			
2	· · · · · · · · · · · · · · · · · · ·		Pert. Top
Liners			Perf. Bottom
			Perf. Top Perf. Bottom
			· ·
APPROXIMATE FRESH WATER APPROXIMATE COAL DEPTHS	Pittsburgh Seam		772-770 feet
IS COAL BEING MINED IN T	HE AREA? YES	BY WHOM? EAC	C- Federal No. 2 Mine
TO DRILL:			
SUBMIT FIVE (5) COPIES OF PLAT.	G OF OG · 1, \$100.00 PERMI	Γ FEE, PERFORMANCE BOI	ND AND PERMANENT COPY
TO DRILL DEEPER OR REDRI	T.T.:		
SUBMIT FIVE (5) COPIES	OF OG - 1 SHOWING OPICE	NAL PERMIT NUMBER AND	PERFORMANCE BOND ON
MUST ALSO BE SUBMITT	TO 1929, A PERMANENT CO	PY OF THE PLAT AND TH	E ORIGINAL WELL RECORD
O FRACTURE - STIMULATE:			
	DICINALLY DOMANT		
BOND, PERMANENT PLAT	ORIGINALLY DRILLED BEFOR TAND ORIGINAL WELL RECO	.E JUNE 5, 1929, FIVE (5) CO	PIES OG - 1, PERFORMANCE
OIL AND/OR GAS WELL O	RIGINALLY DRILLED ON AN MBER, AND PERFORMANCE	D/OP AFTER WAYS 4 4000	FIVE COPIES OG - 1, SHOW-
	d within ninety (90) days of cu	BOND.	
four (24) hours in advance.		•	epector to be nothed twenty.
		,	
The following waiver must nereof.	be completed by the coal opera	itor if the permit is to be issu	red within ten days of receipt
AIVER: I the undersigned, Age			
		LAMI LAMBONY (leves	
We the Eastern As:	and brace on our mine map	s this proposed well location	
providing operator has a	ed and place on our mine map SOCIATED Coal Company ha complied with all rules and regula	ve no objections to mid will	

Resident Engineer
Official Title

STATE OF WEST VIRGINIA DEPARTMENT OF MINES

JUN - 2 1983

OIL AND GAS WELLS DIVISION

OIL & GAS DIVISION

AFFIDAVIT OF PLUGGING AND FILLING ENELLOF MINES

AFFIDAVIT SHOULD BE MADE IN TRIPLICATE, ONE COPY MAILED TO THE DEPARTMENT, ONE COPY TO BE RETAINED BY THE WELL OPERATOR AND THE THIRD COPY (AND EXTRA COPIES IF REQUIRED) SHOULD BE MAILED TO EACH COAL OPERATOR AT THEIR RESPECTIVE ADDRESSES.

1750 Koppers Bldg. Pittsburgh. Pa. Battelle	_
Eastern Royalty Corp. COAL OPERATOR OR OWNER April 11, COAL OPERATOR OR OWNER 1750 Koppers Bldg., Pittsburgh, Pa. Battelle	5 7 0
1750 Koppers Bldg., Pittsburgh, Pa. Battelle	9 83
ADDRESS	istrict
Eastern Royalty Corp. Monongalia	ounty
1750 Koppers Bldg., Pittsburgh, Pa. Well No. EACC-F2-294	ounty
Denny Tennent - 11.0 Acres	
STATE INSPECTOR SUPERVISING PLUGGING William Blosser	Farm
AFFIDAVIT	P*************************************
STATE OF WEST VIRGINIA,	
County of Monongalia ss:	
being first duly sworn according to land and MeLy, ~ R Eddy	
being hist day sworn according to law depose and say that they are experienced in the wor	rk of
Diugging and filling oil and gas wells and wave complemed have Chiglen Brothons	
well operator, and participated in the work of plugging and filling the above well, that said	work
was commenced on the 2 nd day of March 10.83	agod
and filled in the following manner:	ggeu
AND OR ZONE RECORD FILLING MATERIAL PLUGS USED CASING	
FORMATION SIZE & KIND CSG	CSG
Cleaned well to a total depth of 1820 ft.	LEFT IN
(2) Ran 11 nin to a 3 - 11 0 4000 du	
25 have of mol 50 have of all	
Pulled 15 thints of last mine to a suit of the control of the cont	t the
(3) Tagged cement at 1651'-4"; pumped 2 bags of gel,	
pulled 37 inints of 8" nine (1 0001 5" of 8" mars a)	
pulled 37 joints of 8" pipe (1.009'-5" of 8" pulled)	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 42" pipe to a depth of 1066'-2":	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement.	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 4½" to a depth of 884'-7";	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. 5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface.	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. 5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. 6) Set latch down wiper plug at a depth of 853'-3".	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. 5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. 6) Set latch down wiper plug at a depth of 853'-3".	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. 5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. 6) Set latch down wiper plug at a depth of 853'-3".	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 4½" pipe dry to a depth of 853'-3".	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. 5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. 6) Set latch down wiper plug at a depth of 853'-3". 7) Bailed inside of 4½" pipe dry to a depth of 853'-3".	
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. 5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. 6) Set latch down wiper plug at a depth of 853'-3". 7) Bailed inside of 4½" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 4½" x 2" swedge with a 2" s	itop at
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 4½" pipe dry to a depth of 853'-3". COAL SEAMS DESCRIPTION OF MONUMENT Pittsburgh 770-776 ft. Liz x 2" swedge with a 2" s the surface. 2" pipe with	a meta
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bar of gel, 150 bags of chem comp. cement. 5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. 6) Set latch down wiper plug at a depth of 853'-3". 7) Bailed inside of 4½" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 4½" x 2" swedge with a 2" s the surface. 2" pipe with	a meta
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 4½" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 4½" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to th	a meta
pulled 37 jbints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 jbints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 4½" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 1½" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to th pipe.	a meta ne 2"
pulled 37 jbints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 4½" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 4½" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to th pipe. and that the work of plugging and filling said well was completed on the 29 th day	a meta ne 2"
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bas of gel, 150 bass of chem comp. cement. (5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bass of portland cement, 150 bass of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 42" pipe dry to a depth of 853'-3". COAL SEAMS DESCRIPTION OF MONUMENT 12" x 2" swedge with a 2" set the surface. 2" pipe with plate monument welded to the pipe. Ind that the work of plugging and filling said well was completed on the 29 th day March 1983.	a meta ne 2"
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 4½" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 4½" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 4½" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 4½" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to the pipe.	a meta ne 2"
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 42" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 42" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to the pipe. and that the work of plugging and filling said well was completed on the 29 th day March , 19 83	a meta ne 2"
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 42" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 42" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to th pipe. and that the work of plugging and filling said well was completed on the 29 th day March ,19 83 And further deponents saith not.	a meta ne 2"
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bar of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 42" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 12" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to th pipe. and that the work of plugging and filling said well was completed on the 29 th day March , 19 83	a meta ne 2"
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) (4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bar of gel, 150 bags of chem comp. cement. (5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. (6) Set latch down wiper plug at a depth of 853'-3". (7) Bailed inside of 42" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 42" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to the pipe. and that the work of plugging and filling said well was completed on the 29 th day March , 19 83 And further deponents saith not. Sworn to and subscribed before me this Itt day of Ak31' ,19 £	a meta
pulled 37 joints of 8" pipe (1,009'-5" of 8" pulled) 4) Pulled 20 joints of 42" pipe to a depth of 1066'-2"; pumped 1 bag of gel, 150 bags of chem comp. 5) Pulled 6 joints of 42" to a depth of 884'-7"; pumped 700 bags of portland cement, 150 bags of chem comp. cement to the surface. 6) Set latch down wiper plug at a depth of 853'-3". 7) Bailed inside of 42" pipe dry to a depth of 853'-3". COAL SEAMS Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT Pittsburgh 770-776 ft. DESCRIPTION OF MONUMENT 142" x 2" swedge with a 2" s the surface. 2" pipe with plate monument welded to th pipe. d that the work of plugging and filling said well was completed on the 29 th day March ,19 83 And further deponents saith not. Sworn to and subscribed before me this 2 day of 2 kg.1 ,19 &	a meta