

COMPANY DECIDNATED ACERT RORFD

WELL OPERATOR CONSOLIDATION, COAL

STATE OF WEST VIRGINIA DEPARTMENT OF MINES



AFFIDAVIT OF PLUGGING AND FILLING WELLDEPARTMENT OF ENERGY

Canacillation C	oal Company	Consoli	dation Coal Com	pany	
	TATOR OR OWNER		NYME ON METER ONE		
P. O. Box 1314,	Morgantown, WV 26507-1314	P. O. B	Box 1314, Morgan	town, WV 2	<u> 26507-1</u> 31
	ADDRESS	Λugu	st-8		<u> 85</u>
COAL OP	Coal Company.		WELL AND LOC	ATION	
.G. Box 1314	<u> </u>	_Clay			District
Jesse Gine	ADDRESS	Mono	ngalia		County
	PROPERTY OWNER		_		
Rt.2 , Fairi	1 OW, W. Va. 26570	Well No.	M1-363		
	ADDRESS				Farm
_	Don	Ellis			
TATE INSPECTOR S	OF ERVISING 1 DOGGING				
	AFFIDA	AVIT			
TATE OF WEST	\				
ounty of Monon	galia				
David D.	Yost according to law depose a	nd Lar nd say tha	ry L.Yost	nced in the	work of
			Consellaation	i coal co	
ALL AMARSIAR SHA I	iarnendauen in me work or brok	P			
es commenced on	the 9th day of July		19.85, and that t	he well was	plugged
d filled in the fol	lowing manner:				
D OR ZONE RECORD	FILLING MATERIAL		PLUGS USED	CA	BING
PORMATION	Pulled 2135' of rods;	2160 '	STZE & KIND	PULLED	LEFT IM
	of 2 3/8" tubing: 176	1' of	Rods 2 3/8"	2135	
	5½" casing; 1553' of		ng	<u> </u>	
		1	1	11 1761	l
	and 194' of 8" casing	•	$\frac{5\frac{1}{2}!!}{7!!}$	1761	1
	and 194' of 8" casing Cleaned wellbore to 2	190'	7"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'.	190'. Pumped	7"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190	190'. Pumped rough	7" 8"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a	190'. Pumped rough t 1815'	7" 8"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s	190!. Pumped rough t 1815!	7" 8"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows: 950' of 45"c	190'. Pumped rough t 1815' tring a	7"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows: 950' of 45"c 792' of 2 3/8" tubing	190'. Pumped rough t 1815' tring asing; Latch	7" 8" s: down	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows: 950' of 45"c	190'. Pumped rough t 1815' tring asing; Latch	7"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows: 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8	190'. Pumped rough t 1815' tring asing; Latch '; Swed ement t	7"	1553'	
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows: 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks	190'. Pumped rough t 1815' tring asing; Latch '; Swed ement t 25 sack of Thi	7"	1553'	8/20
	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928'; Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh.	7"	1553'	8/2
COAL SEAMS	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,&	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh.	7"	1553' 194'	
Pittsburgh-	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928'; Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh.	7"	1553' 194' on or monum	with
Pittsburgh- ,800'	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,&	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh.	7"	1553' 194' con or monum	with
Pittsburgh- ,800'	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,&	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh.	7"	1553' 194' con or monum	with
Pittsburgh- ,800'	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,& monument.	190'. Pumped rough t 1815' tring asing; Latch '; Swed ement t 25 sack of Thi sh. set	7"	1553' 194' on or mynum " casing sol M1-36	y with
Pittsburgh- ,800'	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,& monument. cof plugging and filling said	190'. Pumped rough t 1815' tring asing; Latch '; Swed ement t 25 sack of Thi sh. set	7"	1553' 194' on or mynum " casing sol M1-36	y with
Pittsburgh- ,800' and that the world	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928'; Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,& monument. cof plugging and filling said	190'. Pumped rough t 1815' tring asing; Latch '; Swed ement t 25 sack of Thi sh. set	7"	1553' 194' on or mynum " casing sol M1-36	y with
oPittsburgh= .800'	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,& monument. cof plugging and filling said	190'. Pumped rough t 1815' tring asing; Latch '; Swed ement t 25 sack of Thi sh. set	7"	1553' 194' on or mynum " casing sol M1-36	y with
Pittsburgh- ,800' and that the worl July And further d	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,& monument. c of plugging and filling said	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh. set	7"	1553' 194' on or monum s' casing sol M1-36 P	with 3. day of
Pittsburgh- ,800! und that the worl July And further d	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows: 950' of 4½"c 792' of 2 3/8" tubing at 928': Float at 950 at 950'. Circulated c surface as follows: 8 of Foz Mix: 365 sacks 1,000 gal. of mud flu Let set, bailed dry,& monument. c of plugging and filling said	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh. set	7"	1553' 194' on or monum s' casing sol M1-36 P	y with
Pittsburgh- ,800' , und that the work July And further d	Cleaned wellbore to 2 Ran tubing to 2190'. 90 sacks of cement th tubing. Tagged plug a Ran coal protection s follows; 950' of 4½"c 792' of 2 3/8" tubing at 928'; Float at 950 at 950'. Circulated c surface as follows; 8 of Foz Mix; 365 sacks 1,000 gal. of mud flu Let set, bailed dry,& monument. c of plugging and filling said	190'. Pumped rough t 1815' tring a asing; Latch '; Swed ement t 25 sack of Thi sh. set	7"	1553' 194' 194' on or mynum 5" casing 301 M1-36 P	with 3. day of