



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
www.dep.wv.gov

November 19, 2015

## FINAL INSPECTION REPORT

### Plugging Permit Cancelled

MOUNTAIN COUNTRY PARTNERS, LLC,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-8701591, issued to MOUNTAIN COUNTRY PARTNERS, LLC, and listed below has been received in this office. The permit has been cancelled as of 11/17/2015.

James Martin  
Chief

Operator: MOUNTAIN COUNTRY PARTNERS, LLC  
Operator's Well No: SCHOOLCRAFT 163  
Farm Name: BODE, LEO  
**API Well Number: 47-8701591**  
Date Issued: 12/21/2011

Date Cancelled: 11/17/2015

Promoting a healthy environment.

11/20/2015

INSPECTORS PERMIT SUMMARY FORM

PAGE 1

GPS YES [ ] NO [ ]

DATE STARTED/LOCATION: [ ] API #: 47-87-01591 WELL NO. Schoolcraft 163

DILLING COMMENCED: [ ] OPERATOR: MCP

TD DATE: [ ] DEPTH: [ ] FARM: Leo Bode

WATER DEPTHS [ ] COAL DEPTHS [ ]

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
- A. CONSTRUCTION YES [ ] NO [ ] (2 PTS) B. DRILLING YES [ ] NO [ ] (2 PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [ ] NO [ ] (4 PTS)

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [ ] NO [ ] (4 PTS)

4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
- A. ROAD DITCHES (1)\_ (2)\_ (3)\_ (4)\_ (PTS) B. CROSS DRAINS (1)\_ (2)\_ (3)\_ (4)\_ (5)\_ (PTS)
- C. CULVERTS (1)\_ (2)\_ (3)\_ (4)\_ (5)\_ (PTS) D. CREEK CROSSINGS (1)\_ (2)\_ (3)\_ (PTS)
- E. DIVERSION DITCHES (1)\_ (2)\_ (3)\_ (PTS) F. BARRIERS (1)\_ (2)\_ (3)\_ (PTS)
- G. TEMPORARY SEEDING YES [ ] NO [ ] (10 PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS)

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [ ] NO [ ] (2 PTS)
- THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [ ] NO [ ] (9 PTS)

7. RECLAMATION:
- A. ROADWAY (1)\_ (2)\_ (3)\_ (PTS) B. LOCATION (1)\_ (2)\_ (3)\_ (PTS)
- C. PITS (1)\_ (2)\_ (3)\_ (PTS) D. PIPELINES (1)\_ (2)\_ (3)\_ (PTS)
- E. TANK DIKES (1)\_ (2)\_ (3)\_ (PTS) F. API INSTALLED YES OR NO 3 (PTS)
- G. ADEQUATE SEEDING MATERIALS (1)\_ (2)\_ (3)\_ (PTS)
- H. WAS SEED BED ADEQUATE (1)\_ (2)\_ (3)\_ (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS)

8. WAS RECLAMATION COMPLETED WITHIN:
- 6 MTHS OF TD 6 PTS ONLY; 4 MTHS OF TD 12 PTS ONLY; 2 MTHS OF TD 19 PTS ONLY.
- MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS)

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: 0

INSPECTIONS:

New & Plugseed

Received

NOV 17 2015

Office of Oil and Gas WV Dept. of Environmental Protection

11-17-15 DATE RELEASED

Inspector Signature

INSPECTOR

11/20/2015