



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street SE
Charleston, WV 25304
(304) 926-0450
(304) 926-0452 fax

Earl Ray Tomblin, Governor
Randy C. Huffman, Cabinet Secretary
www.dep.wv.gov

October 22, 2015

FINAL INSPECTION REPORT

Well Permit Cancelled

CNX GAS COMPANY LLC ,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-103289, issued to CNX GAS COMPANY LLC , and listed below has been received in this office. The permit has been cancelled as of 10/22/2015.

James Martin
Chief

Operator: CNX GAS COMPANY LLC
Operator's Well No: AUD3BHS
Farm Name: MIKE ROSS, INC.
API Well Number: 47-103289
Date Issued: 03/28/2013

Date Cancelled: 10/22/2015

Promoting a healthy environment.

10/23/2015

INSPECTORS PERMIT SUMMARY FORM

GPS YES |] NO |]

Received

OPERATOR: CNX GAS COMPANY LLC

FARM: MIKE ROSS, INC.

Well No: AUD3BH8

COAL DEPTHS: _____

Office of Oil and Gas

WV Dept of Environmental Protection

OCT 22 2015

DATE STARTED/LOCATION: 4-9-13

DRILLING COMMENCED: _____

TO DATE: _____

WATER DEPTHS: _____

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:

A. CONSTRUCTION YES |] NO |] (2_PTS) B. DRILLING YES |] NO |] (2_PTS)

2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES |] NO |] (2_PTS)

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES |] NO |] (4_PTS)

4. CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS) B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS) C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS) D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS) E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS) F. BARRIERS (1)_ (2)_ (3)_ (PTS) G. TEMPORARY SEEDING YES |] NO |] (10_PTS)

POINTS AVAILABLE FOR QUESTION 4: (33_PTS)

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES |] NO |] (2_PTS)

6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES |] NO |] (9_PTS)

7. RECLAMATION: A. ROADWAY (1)_ (2)_ (3)_ (PTS) B. LOCATION (1)_ (2)_ (3)_ (PTS) C. PITS (1)_ (2)_ (3)_ (PTS) D. PIPELINES (1)_ (2)_ (3)_ (PTS) E. TANK DIKES (1)_ (2)_ (3)_ (PTS) F. API INSTALLED YES |] NO |] (3_PTS) G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS) H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS)

POINTS AVAILABLE FOR QUESTION 7: (24_PTS)

8. WAS RECLAMATION COMPLETED WITHIN: 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY;

POINTS AVAILABLE FOR QUESTION 8: (19_PTS)

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

DATE RELEASED

10-22-13

INSPECTOR'S SIGNATURE

[Signature]