



## west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

January 12, 2016

## FINAL INSPECTION REPORT

## Well Permit Cancelled

MOUNTAINEER KEYSTONE, LLC,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-103316, issued to MOUNTAINEER KEYSTONE, LLC, and listed below has been received in this office. The permit has been cancelled as of 1/11/2016.

James Martin Chief

Cinei

Operator: MOUNTAINEER KEYSTONE, LLC

Operator's Well No: HOWDERSHELT 202

Farm Name: HOWDERSHELT, MELVIN & REN

API Well Number: 47-103316

Date Issued: 01/09/2014

Date Cancelled: 01/11/2016

Promoting a healthy environment.

IR - 26 (REV 08)

## INSPECTORS PERMIT SUMMARY FORM

GPS YES | NO | |

DATE STARTED/LOCATION:			OPERATOR:	MOUNTAINEER KEYSTONE, LLC		
DRILLING COMMENCED:		FARM:	HOWDERSHELT, MELVIN & RENEE			
TO DATE:		DEPTHS:	Well No:	HOWDERSHELT 202		
WATER DEPTHS:		•	COAL DEPTH	S		
4-1	2.1 AND 35CSR 4-16 AND	THE GENERAL WATER	R POLLUTION CONT		NS 35CSR	
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.						
1.	DID OPERATOR GIVE P					
	A. CONSTRUCTION		[ ] NO[ ] (2_PTS		(4_PTS)	
	B. DRILLING	·	[ ] NO [ ] (2_PTS			
2.	WAS THE TIMBER CUT BEFORE DIRT WORK S'	, STACKED, AND BRUS TARTED? YES	H USED FOR SEDIM	ient Barriers IS)	(4_PTS)	
3.	ARE ALL LOCATION AN	ND/OR ROAD BANKS B	EING SLOPED? YE	S[] NO[] (4_PTS)	(4_PTS)	
4.	WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?  A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS)  C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) D. CREEK CROSSINGS (1)_(2)_(3)_(PTS)  E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS)  G. TEMPORARY SEEDING YES[] NO[] (10_PTS)					
			POINTS AVAILABI	E FOR QUESTION 4:	(33_PTS)	
5.	HAS TOP SOIL (IF ANY)	BEEN STOCKED PILE	D? YES[]	NO [ ] (2_PTS)	(2_PTS)	
6.	IS THE PIT PROPERLY I	NSTALLED AND MAIN	TAINED? YES[]	NO[] (9_PTS)	(9_PTS)	
7.	RECLAMATION:					
	A. ROADWAY	(1)_(2)_(3)_(PTS)	B. LOCATION	(1)_(2)_(3)_(PT	S)	
	C. PITS	(1)_(2)_(3)_(PTS)		(1)_(2)_(3)_(PT		
	E. TANK DIKES	(1)_(2)_(3)_(PTS)	F. API INSTAL	LED YES[] NO[	] (3_PTS)	
	G. ADEQUATE SEEDIN		(2)_(3)_(PTS)			
	H. WAS SEED BED AD	-	(2)_(3)_(PTS)			
			POINTS AVAILABL	E FOR QUESTION 7:	(24_PTS)	
8.	WAS RECLAMATION COMPLETED WITHIN:  MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY;					
POINTS AVAILABLE FOR QUESTION 8: (19_PT						
3	OTAL MAXIMUM POSS	SIBLE SCORE OF 99.	TOTAL	RECLAMATION SCORE	* * * * * * * * * * * * * * * * * * *	
	1-11-11			I Same	M	
	DATE RELEASE	<u>D</u>	Tr.	SPECTOR'S SIGNATURE	3	
	CANCE	-640				

RECORD INSPECTIONS TO THIS WELL ON PAGE 2