



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57<sup>th</sup> Street, S.E.  
Charleston, WV 25304  
(304) 926-0450  
fax: (304) 926-0452

Austin Caperton, Cabinet Secretary  
[www.dep.wv.gov](http://www.dep.wv.gov)

Wednesday, January 16, 2019  
NOTICE OF PERMIT CANCELLATION  
Vertical / Plugging

EQT PRODUCTION COMPANY  
625 LIBERTY AVE., SUITE 1700

PITTSBURGH, PA 15222

Re: Permit cancellation for 7609  
47-007-00028-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-007-00028-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 1/16/2019 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

A blue ink signature of James A. Martin.

James A. Martin  
Chief

Operator's Well Number: 7609  
Farm Name: ROLLISON, L. A.  
U.S. WELL NUMBER: 47-007-00028-00-00  
Vertical Plugging  
Date Cancelled: 1/16/2019

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED \_\_\_\_\_  
PLUGGING COMPLETED NA  
VERBAL PERMISSION ON \_\_\_\_\_

OPERATOR: EQT PRODUCTION COMPANY  
FARM: ROLLISON, L. A.  
WELL NO: 7609

- 1. IS COAL BEING MINED IN THE AREA? YES NO N/A
- 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
  - A. BOTTOM HOLE PLUGGED YES NO N/A
  - B. 100' PLUGS YES NO N/A
  - C. LATEX PLUGS USED FOR H<sub>2</sub>S GAS YES NO N/A
  - D. PROPER PLUGS THROUGH COAL SEAMS YES NO N/A
  - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES NO N/A
  - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A

| TYPE                                 | FROM | TO | PIPE REMOVED |
|--------------------------------------|------|----|--------------|
| <i>Not Plugged</i>                   |      |    |              |
| <i>Permit Cancelled for Transfer</i> |      |    |              |

- 3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NO
- 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES NO
- 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NO
- 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
- 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NO
- 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?
 

|                   |     |    |                          |     |    |
|-------------------|-----|----|--------------------------|-----|----|
| A. RECLAIMED      | YES | NO | B. FENCES REPLACED       | YES | NO |
| C. MULCHED        | YES | NO | D. PROPER DRAINAGE       | YES | NO |
| E. SEEDED         | YES | NO | F. ALL EQUIPMENT REMOVED | YES | NO |
| G. PIT BACKFILLED | YES | NO |                          |     |    |

1/16/19  
DATE RELEASED

*[Signature]*  
INSPECTOR'S SIGNATURE