Buffallo Dist?

......District, Brooke County, W. Va. At Beech Bottom.
Completed, 1903.
Authority, T. W. Carmichael.
Wheeling Quadrangle. Data contained in letter to Director dated Feb. 20, 1903.

Thickness. Depth.

Hard rock roof

Coal

Fire clay

8 **-** 358 15 **-** 373

STRAT INFO: FORMATION	PAYS INFO: ACTIVITY PRODUCT	OGWATER (INCLUDE QUALITY, DEPTH, QUANTITY)	OWNERS: INFO: STATUS: ( C ) OPERATOR CODE: (	DEEPEST FORMATION: AT TOTAL DEPTH:	DEPTHS: TOTAL FOOTAGE: 373	ROCK NATURAL (PSI): PRESSURE: TREATED (PSI):	OPEN GAS-BEFORE TREATMENT (MCFIOW: GAS-AFTER TREATMENT (MCFIO)	FIELD: ( )	INITIAL: FENAL:	CLASSIFICATION:	COMPLETION INFO:	ID: COUNTY: (009)
FM Q DEPTH (depth for Thick) DEPTH QUALITY	UCT TOP FORMATION TOP DEPTH BOTTOM DEPTH BOTTOM FORMATION	H, QUANTITY) if available:	DATE: (MM/DD/YYYY): //1903 SURFACE OWNER:: OIL&GAS OWNER: COMPANY NUMBER: (	EPTH: ( ) DEEPEST FORMATION TESTED: ( ))	NEW FOOTAGE: 373 EXPLORATORY FOOTAGE:	TIME (NATURAL, IN HOURS):	(MCFPD):  OIL-BEFORE TREATMENT: (BOPD):  OIL-AFTER TREATMENT (BOPD):	BATCH: / / YEAR RPTD:	SPUD: 7 7  COMP: //1903  COMPL METH:	אאי/ ממ/אא	ELEVATION: ELEVATION TYPE: COMP FLAG:	PERMIT: 70009 SUFFIX: Ø REASSIGNE
THICKNESS THICKNESS QUALITY ELEVATION TYPE	RMATION BEFORE AFTER			1	~ ·	I LONGITUDE (DDMM Miles_West)  ! ! ! ! ! OTTADRANGLE: ( ) Wheeling.	! 15' LATITUDE (DDMM Miles_South)	;	LONGITUDE (DDMM.M Miles_West)	7.5' LATITUDE (DDMM.M Miles_South)	! LOCATION INFO: TAX DISTRICT: ( )	REASSIGNED COUNTY/PERMIT #: