12-10-18

PAGE 1			GPS YES NO	
DATE STARTED/LOCATION:		API #: 47-	011-01009-00-00 WELL NO. TA	ASSEN 5
DRILLING COMMENCED:	OP	ERATOR:	KEYROCK ENERGY LLC	
TD DATE:	DEPTH:		FARM: JACQUELINE TASSEN	1
WATER DEPTHS QUESTIONS FOR THIS REPORT	ARE IN ACCORDANCE		L DEPTHS DE 22-6-30	
AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT				
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.				
1. DID OPERATOR GIVE PROPE A. CONSTRUCTION YES	ER NOTICE TO INSPECT			
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE				(4 PTS)
DIRT WORK STARTED? YES		ED FOR SED	— —	(4 PTS)
3. ARE ALL LOCATION AND/O	OR ROAD BANKS BEING	SLOPED?	YES NO (4_PTS)	(4 PTS)
4. CONSTRUCTION:	MENT CONTROL CTRU	CTUDES DD	NDEDLY DICTALLED A (A DITA DIE	D9
WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS)				
C. CULVERTS (1)_(2)_(3)_(4)_ E. DIVERSION DITCHES (1)_(3)_(4)_			OSSINGS (1)_(2)_(3)_(PTS) (1) (2) (3) (PTS)	
G. TEMPORARY SEEDING YE			AVAILABLE FOR QUESTION 4:	(33 PTS)
5. HAS TOP SOIL (IF ANY) BEE	N STOCKED PILED? Y	ES NO	(2_PTS)	(2 PTS)
6. IS THE PIT PROPERLY INSTA	ALLED AND MAINTAIN	ED? YES	NO (9_PTS)	(9 PTS)
7. RECLAMATION:		3.1 × 10 × 20 × 40	A) (PTO)	
	D. PIPELINE	ES (1) (2) (3)_(PTS)	
E. TANK DIKES (1)_(2)_(3)_(F G. ADEQUATE SEEDING MATE			S OR NO 3_(PTS)	
H. WAS SEED BED ADEQUATE			VAILABLE FOR QUESTION 7:	(24 PTS)
8 WAS RECLAMATION COMP	LETED WITHIN:			
MTHS OF TD 6_PTS ONLY	Y; MTHS OF TD 12_	PTS ONLY;	MTHS OF TO 19_PTS ONLY VAILABLE FOR QUESTION 8:	(19 PTS)
TOTAL MAYIMUM POCCI			,	(2212)
TOTAL MAXIMUM POSSI	BLE SCORE OF 99.		TOTAL RECLAMATION	N SCORE:
INSPECTIONS:				
		1	1	
	CN	10	lemit	
		/ .		
1-4-20	Kernyw	lela		
DATE RELEASED	INSPECTOR	R		