



---

**west virginia** department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
[www.dep.wv.gov](http://www.dep.wv.gov)

July 08, 2015

**FINAL INSPECTION REPORT**

**New Well Permit Cancelled**

ADKINS, TEDDY,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-1304724, issued to ADKINS, TEDDY, and listed below has been received in this office. The permit has been cancelled as of 6/1/2015.

James Martin  
Chief

Operator: ADKINS, TEDDY  
Operator's Well No: COX 2  
Farm Name: COX, CARL WARREN  
**API Well Number: 47-1304724**  
Date Issued: 07/14/2010

Date Cancelled: 06/01/2015

**Promoting a healthy environment.**

GPS YES  NO

DATE STARTED/LOCATION:		API #:	47-13-04724	WELL NO.:	Cox 2
DRILLING COMMENCED:		OPERATOR:	Teddy Adkins		
TD DATE:		DEPTH:		FARM:	Carl Warren Cox
WATER DEPTHS		COAL DEPTHS			

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:  
A. CONSTRUCTION YES  NO  (2 PTS)      B. DRILLING YES  NO  (2 PTS)      (4 PTS) \_\_\_\_\_

2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES  NO  (4 PTS)      (4 PTS) \_\_\_\_\_

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES  NO  (4 PTS)      (4 PTS) \_\_\_\_\_

4. CONSTRUCTION:  
WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1  2  3  4  (PTS)      B. CROSS DRAINS 1  2  3  4  5  (PTS)

C. CULVERTS 1  2  3  4  5  (PTS)      D. CREEK CROSSINGS 1  2  3  (PTS)

E. DIVERSION DITCHES 1  2  3  (PTS)      F. BARRIERS 1  2  3  (PTS)

G. TEMPORARY SEEDING YES  NO  (10 PTS)      POINTS AVAILABLE FOR QUESTION 4:      (33 PTS) \_\_\_\_\_

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES  NO  (2 PTS)      (2 PTS) \_\_\_\_\_

6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES  NO  (9 PTS)      (9 PTS) \_\_\_\_\_

7. RECLAMATION:

A. ROADWAY 1  2  3  (PTS)      B. LOCATION 1  2  3  (PTS)

C. PITS 1  2  3  (PTS)      D. PIPELINES 1  2  3  (PTS)

E. TANK DIKES 1  2  3  (PTS)      F. API INSTALLED YES  NO  (3 PTS)

G. ADEQUATE SEEDING MATERIALS 1  2  3  (PTS)

H. WAS SEED BED ADEQUATE 1  2  3  (PTS)      POINTS AVAILABLE FOR QUESTION 7:      (24 PTS) \_\_\_\_\_

8. WAS RECLAMATION COMPLETED WITHIN:

6 MTHS OF TD \_\_\_ 6 PTS ONLY;    4 MTHS OF TD \_\_\_ 12 PTS ONLY;    2 MTHS OF TD \_\_\_ 19 PTS ONLY.

MAXIMUM POINTS AVAILABLE FOR QUESTION 8:      (19 PTS) \_\_\_\_\_

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: \_\_\_\_\_

INSPECTIONS:

---

Cancel

---



---

