



STATE OF WEST VIRGINIA
DEPARTMENT OF MINES
OIL AND GAS DIVISION

Quadrangle Centerpoint

Permit No. Dod-1113

WELL RECORD

Oil or Gas Well Gas
(KIND)

Company Allegheny Land & Mineral Company
Address Clarksburg, W.Va.
Farm Allie Curry Acres 43
Location (waters) _____
Well No. A-208 Elev. 1251
District McClellan County Doddridge
The surface of tract is owned in fee by Curry Heirs
Address Clarksburg, W.Va.
Mineral rights are owned by Same
Address _____

Casing and Tubing	Used in Drilling	Left in Well	Packers
Size			Kind of Packer
16	16'	16'	
13			
10	253'		Size of
8 1/4	1381'		
6 5/8			Depth set
5 3/4	2327'	2327'	
3			Perf. top <u>2263</u>
2			Perf. bottom <u>2271</u>
Liners Used			Perf. top _____
			Perf. bottom _____

Drilling commenced April 18, 1964
Drilling completed May 2, 1964
Date Shot _____ From _____ To _____
With _____
Open Flow 10/10ths Water in 1 Inch
_____/10ths Merc. in _____ Inch
Volume 33,000 Cu. Ft.
Rock Pressure 300# lbs. 12 hrs.
Oil Show only bbls., 1st 24 hrs.
WELL ACIDIZED _____

CASING CEMENTED 4 1/2" SIZE 400 No. Ft. 5-16-64 Date
100 Cement, 200# Bentonite, 50# Lime
COAL WAS ENCOUNTERED AT _____ FEET _____ INCHES
_____ FEET _____ INCHES FEET _____ INCHES
_____ FEET _____ INCHES FEET _____ INCHES

WELL FRACTURED May 21, 1964 By Dowell- Water, sand, acid.

RESULT AFTER TREATMENT 100/10 Merc. 2" 1,555 M
ROCK PRESSURE AFTER TREATMENT 590# 12 Hr.
Fresh Water _____ Feet Salt Water 1 bailer per hr. 1508

Formation	Color	Hard or Soft	Top	Bottom	Oil, Gas or Water	Depth	Remarks
Soil			0	10			
Red Rock			10	14			
Lime			14	27			
Red Rock			27	45			
Sand			45	68			
Red Rock			68	85			
Slate & shells			85	112			
Red Rock			112	150			
Lime			150	197			
Red Rock			197	211			
Slate & shell			211	230			
Red Rock			230	254			
Lime			254	335			
Slate & shell Black			335	380			
Sand			380	405			
Slate			405	410			
Lime			410	430			
Red Rock			430	475			
Slate & shell			475	500			
Lime			500	525			
Red Rock			525	535			
Slate			535	540			
Sand			540	570			
Slate			570	590			
Lime			590	638			
Slate			638	645			
Red Rock			645	655			
Lime			655	820			
Slate & shell			720	842			
Slate	Black		842	872			



Formation	Color	Hard or Soft	Top <i>f</i>	Bottom	Oil, Gas or Water	Depth Found	Remarks
Sand			872	903			
Slate & shell			903	915			
Sand			915	945			
Slate & shell			945	1070			
Red Rock			1070	1100			
Sand			1100	1104			
Slate & shell			1104	1170			
Lime			1170	1205			
Sand			1205	1225			
Slate	Black		1225	1265			
Sand			1265	1305			
Slate	Black		1305	1360			
Lime			1360	1372			
Pink Rock			1372	1400			
Lime			1400	1430			
Slate & shell			1430	1508	Salt Water	1508	1 bailer per hour
Sand			1508	1555			
Slate			1555	1570			
Sand			1570	1590			
Slate			1590	1604			
Sand			1604	1640			
Slate & shell			1640	1695			
Sand			1695	1714			
Slate & shell	Black		1714	1750			
Sand			1750	1805			
Slate			1805	1840			
Sand			1840	1893			
Slate & shell			1893	1940			
Lime			1940	1960			
Slate			1960	1995			
Gritty Lime			1995	2018			
Slate & shell			2018	2045			
Red Rock			2045	2060			
Slate & shell			2060	2080			
Red Lime			2080	2090			
Slate & shell			2090	2106			
Little Lime			2106	2120			
Slate			2120	2135			
Broken Lime			2135	2145			
Big Lime			2145	2186			
Sand			2186	2269	Oil	2216-2221	Show
Slate			2269	2274	Gas	2246-2255	Show
Sand			2274	2331	Gas	2255-2265	10/10 W 1"
Total depth				2331			33 M
			4 1/2" casing perforated	2263 to 2271	24 holes		

Date May 28, 19 64
APPROVED Allegheny Land & Mineral Co., Owner
By Claron W. Dawson, Mahone, W.Va.
(Title)