



west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

June 15, 2015

FINAL INSPECTION REPORT

New Well Permit Cancelled

JAY-BEE OIL & GAS,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-1705856, issued to JAY-BEE OIL & GAS, and listed below has been received in this office. The permit has been cancelled as of 6/11/2015.

James Martin Chief

Operator: JAY-BEE OIL & GAS

Operator's Well No: HORNER 1 HA

Farm Name: GLASPELL, MARY L

API Well Number: 47-1705856 Date Issued: 09/30/2009

Date Cancelled: 06/11/2015

Promoting a healthy environment.

PAGE I

GPS YES | NO []

DATE STARTED/LOCATION:		API #:	47:017-05456	WELL NO.	Horner 1 HH
DRILLING COMMENCED:		OPERATOR:	1	Calina	
TD DATE:	DEPTH:		FARM:		
WATER DEPTHS COAL DEPTHS					
QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT					
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.					
1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING: A. CONSTRUCTION YES [] NO [] (2_PTS) B. DRILLING YES [] NO [] (2_PTS)					(4 PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE					(+110)
DIRT WORK STARTED? YES[] NO[] (4_PTS)					(4 PTS)
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_ PTS)					(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? A. ROAD DITCHES (1) (2) (3) (4) (PTS) B. CROSS DRAINS (1) (2) (3) (4) (5) (PTS) C. CULVERTS (1) (2) (3) (4) (5) (PTS) D. CREEK CROSSINGS (1) (2) (3) (PTS) E. DIVERSION DITCHES (1) (2) (3) (PTS) F. BARRIERS (1) (2) (3) (PTS) G. TEMPORARY SEEDING YES [] NO [] (10 PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS)					
5. HAS TOP SOIL (IF ANY) BEE					(2 PTS)
6. IS THE PIT PROPERLY INSTA	ALLED AND MAINT	AINED? YES [] NO[] (9_P	ΓS)	(9 PTS)
7. RECLAMATION: A. ROADWAY (1)_(2)_(3)_(PTC. PITS (1)_(2)_(3)_(PTS) E. TANK DIKES (1)_(2)_(3)_(PG. ADEQUATE SEEDING MATEH. WAS SEED BED ADEQUATE	ERIALS(1)(2)(3)	(PIS)			: (24 PTS)
8. WAS RECLAMATION COMPI 6 MTHS OF TD 6_PTS ONLY	': 4 MTHS OF TD	12_PTS ONLY MUM POINTS A	; 2 MTHS OF T VAILABLE FOR	TD 19_PTS ON QUESTION 8:	LY. : (19 PTS)
TOTAL MAXIMUM POSSIBLE SCORE OF 99. TOTAL RECLAMATION SCORE:					
			IOIAL	, KECLAMIA I	ON 500KB.
INSPECTIONS:					aired
	culed			Dec	SELA
***************************************	DA .			1	n 15 2013
Ala	C				15 200
	}			J.	N .
					and Gas rection
				C	Affice of Oll Bills Project
			Office of Oil and Gas Office of Oil and Gas WV Dept. of Environmental Protection		
				444	
6-11-2015 DATE RELEASED	Bouglas INSPEC	Nembo-			