

west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

February 16, 2016

FINAL INSPECTION REPORT

Horizontal Well Permit Cancelled

WACO OIL & GAS CO INC,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-1706006, issued to WACO OIL & GAS CO INC, and listed below has been received in this office. The permit has been cancelled as of 2/9/2016.

James Martin Chief

Operator: WACO OIL & GAS CO INC

Operator's Well No: C G DAVIS 1H2037


Farm Name: GASKINS, DOROTHY JUNE (LIFI

API Well Number: 47-1706006

Date Issued: 03/31/2011

Date Cancelled: 02/09/2016

Promoting a healthy environment.



INSPECTORS PERMIT SUMMARY FORM

GPS YES [] NO []

DA	TE STARTED/LOCATION: Never Driller	0	PERATOR:	WACO OIL & GAS CO II	NC	
	ILLING COMMENCED:	HALE OF THE STREET	ARM:	GASKINS, DOROTHY J	UNE (LIFE)	
TO DATE: DEPTHS:			/ell No:	C G DAVIS 1H2037		
WA	TER DEPTHS:	OAL DEPTHS				
QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.						
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.						
1.	DID OPERATOR GIVE PROPER NOTICE TO IN	NG YES[] NO[] (2_PTS)		E FOLLOWING:)WING:	
				(4_PTS)		
	B. DRILLING YES					
2.		AS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS FORE DIRT WORK STARTED? YES [] NO [] (2_PTS) (4_PTS)				
3.	ARE ALL LOCATION AND/OR ROAD BANKS	BEING SI	LOPED? YES] NO[] (4_PTS)	(4_PTS)	
4.	CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS) C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) D. CREEK CROSSINGS (1)_(2)_(3)_(PTS) E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS) G. TEMPORARY SEEDING YES[] NO[] (10_PTS)					
	POINTS AVAILABLE FOR QUESTION 4: (33_PTS)					
5.	HAS TOP SOIL (IF ANY) BEEN STOCKED PILE	ED?	YES[] N	O[] (2_PTS)	(2_PTS)	
6.	S THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [] NO [] (9_PTS) (9_PTS)					
7.	RECLAMATION:	RECLAMATION:				
	A. ROADWAY (1)_(2)_(3)_(PTS) C. PITS (1)_(2)_(3)_(PTS) E. TANK DIKES (1)_(2)_(3)_(PTS)	D.	LOCATION PIPELINES API INSTALLE	(1)_(2)_(3)_(PTS)	ECEIVED	
	G. ADEQUATE SEEDING MATERIALS (1)	_(2)_(3)_((PTS)	FE.	R 0 9 2016	
	H. WAS SEED BED ADEQUATE (1)	_(2)_(3)_((PTS)			
	POINTS AVAILABLE FOR QUESTION 7:WV Quarters of Environmental Protection					
8.	WAS RECLAMATION COMPLETED WITHIN: 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY;					
POINTS AVAILABLE FOR QUESTION 8: (19_PTS)						
T	TOTAL MAXIMUM POSSIBLE SCORE OF 99. TOTAL RECLAMATION SCORE:					
	DATE RELEASED- Cancelled	9	hoqua li	honta PECTOR'S SIGNATURE		