



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary
www.dep.wv.gov

Friday, October 28, 2022
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / Horizontal 6A Well - 1

ANTERO RESOURCES APPALACHIA CORPORATION

Re: Permit cancellation for TRENT UNIT 1H
47-017-06307-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-017-06307-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 10/28/2022 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

James A. Martin
Chief

Operator's Well Number: TRENT UNIT 1H
Farm Name: TRENT, JOHN S. JR. & JACQUELIN S.
U.S. WELL NUMBER: 47-017-06307-00-00
Horizontal 6A Horizontal 6A Well - 1
Date Cancelled: 10/28/2022

Promoting a healthy environment.

10/28/2022

PAGE 1

GPS YES ___ NO ___

DATE STARTED/LOCATION:		API #:	4701706307	WELL NO.	Trent 1 H
DRILLING COMMENCED:	Canceled	OPERATOR:	Antero Resources Corporation		
TD DATE:		DEPTH:		FARM:	J S Jr & J S Trent
WATER DEPTHS			COAL DEPTHS		

WATER DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30

AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 A. CONSTRUCTION YES ___ NO ___ (2 PTS) B. DRILLING YES ___ NO ___ (2 PTS) (4 PTS) _____

2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES ___ NO ___ (4 PTS) (4 PTS) _____

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES ___ NO ___ (4 PTS) (4 PTS) _____

4. CONSTRUCTION:

WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1__ 2__ 3__ 4__ (PTS) B. CROSS DRAINS 1__ 2__ 3__ 4__ 5__ (PTS)
 C. CULVERTS 1__ 2__ 3__ 4__ 5__ (PTS) D. CREEK CROSSINGS 1__ 2__ 3__ (PTS)
 E. DIVERSION DITCHES 1__ 2__ 3__ (PTS) F. BARRIERS 1__ 2__ 3__ (PTS)
 G. TEMPORARY SEEDING YES ___ NO ___ (10 PTS) **POINTS AVAILABLE FOR QUESTION 4: (33 PTS) _____**

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES ___ NO ___ (2 PTS) (2 PTS) _____

6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES ___ NO ___ (9 PTS) (9 PTS) _____

7. RECLAMATION:

A. ROADWAY 1__ 2__ 3__ (PTS) B. LOCATION 1__ 2__ 3__ (PTS)
 C. PITS 1__ 2__ 3__ (PTS) D. PIPELINES 1__ 2__ 3__ (PTS)
 E. TANK DIKES 1__ 2__ 3__ (PTS) F. API INSTALLED YES ___ NO ___ (3 PTS)
 G. ADEQUATE SEEDING MATERIALS 1__ 2__ 3__ (PTS)
 H. WAS SEED BED ADEQUATE 1__ 2__ 3__ (PTS) **POINTS AVAILABLE FOR QUESTION 7: (24 PTS) _____**

8. WAS RECLAMATION COMPLETED WITHIN:

A. CONVENTIONAL:

6 MTHS OF TD ___ 6 PTS ONLY; 4 MTHS OF TD ___ 12 PTS ONLY; 2 MTHS OF TD ___ 19 PTS ONLY.

B. HORIZONTAL:

3 YRS OF PAD COMPLETION ___ 19 PTS ONLY; 4 YRS OF PAD COMPLETION ___ 16 PTS ONLY;
5 YRS OF PAD COMPLETION ___ 13 PTS ONLY

MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

Canceled 7/24/2022
DATE RELEASED

Douglas Newlon
INSPECTOR

10/28/2022