

## west virginia department of environmental protection

Office of Oil and Gas 601 57th Street, S.E. Charleston, WV 25304 (304) 926-0450 fax: (304) 926-0452 Jim Justice , Governor Austin Caperton , Cabinet Secretary www.dep.wv.gov

Thursday, March 16, 2017 NOTICE OF PERMIT CANCELLATION Horizontal 6A / Horizontal 6A Well - 1

ANTERO RESOURCES CORPORATION (A) 1615 WYNKOOP STREET

DENVER, CO 80202

Re: Permit cancellation for MILO UNIT 2H

47-017-06569-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-017-06569-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 8/11/2014

If there are any questions, please feel free to contact me at (304) 926-0450.

James A. Martin

Chief

Operator's Well Number: MILO UNIT 2H Farm Name: HILL, PHILLIP N. ET AL U.S. WELL NUMBER: 47-017-06569-00-00

Horizontal 6A / Horizontal 6A Well - 1

Date Cancelled: 8/11/2014

Promoting a healthy environment.

| PAGE 1   |                       |                   | GPS YES NO                             |               |
|--|-----------------------|-------------------|--|---------------|
| DATE STARTED/LOCATION:   |                       | API #:            | 47-017-06569 WELL NO.                  | MILO Unit 2 H |
| DRILLING COMMENCED:  |                       | OPERATOR:         | Antero Resources                       |               |
| TD DATE:   | DEPTH:                |                   | FARM: Phillip N Hill et al             |               |
| WATER DEPTHS   |                       |                   | AL DEPTHS                              |               |
| QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30<br>AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT |                       |                   |  |               |
| POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.  |                       |                   |  |               |
| 1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:  |                       |                   |  |               |
| A. CONSTRUCTION YES  | NO $\bigcirc$ (2 PTS) | B. DRILLING       | G YES $\bigcirc$ NO $\bigcirc$ (2 PTS) | (4 PTS)       |
| 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE  |                       |                   |  |               |
|  |                       |                   |  | (4 PTS)       |
| 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4 PTS) (4 PTS)   |                       |                   |  |               |
| 4. CONSTRUCTION: WERE THE FOLLOWING SED  | IMENT CONTROL ST      | RUCTURES PR       | ROPERLY INSTALLED/MAINTAIN             | IED?          |
| A. ROAD DITCHES 1 2 3 4 (PTS)  B. CROSS DRAINS 1 2 3 4 5 (PTS)   |                       |                   |  |               |
| C. CULVERTS 1 2 3 4 5 (PTS) D. CREEK CROSSINGS 1 2 3 (PTS)   |                       |                   |  |               |
| E. DIVERSION DITCHES 1   | 2 3 (PTS)             | F. BARR           | JERS 1 2 3 (PTS)                       |               |
| <del></del>  | ES NO Q (10 PT        | rs) <b>Points</b> | AVAILABLE FOR QUESTION 4:              | (33 PTS)      |
| 5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES O NO (2 PTS)  |                       |                   |  | (2 PTS)       |
| 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES <b>O</b> NO <b>O</b> (9 PTS)  |                       |                   |  | (9 PTS)       |
| 7. RECLAMATION:  |                       |                   |  |               |
| A. ROADWAY 1 2 3 (PTS) B. LOCATION 1 2 3 (PTS)   |                       |                   |  |               |
| C. PITS 1 2 3 (PTS) D. PIPELINES 1 2 3 (PTS)   |                       |                   |  |               |
| E. TANK DIKES 1 2 3 (PTS) F. API INSTALLED YES NO (3 PTS)  |                       |                   |  |               |
| G. ADEQUATE SEEDING MATERIALS 1 2 3 (PTS)  |                       |                   |  |               |
| H. WAS SEED BED ADEQUAT  |                       |                   | AVAILABLE FOR QUESTION 7:              | (24 PTS)      |
| 8. WAS RECLAMATION COMI  | PI FTFD WITHIN:       |                   |  |               |
| 6 MTHS OF TD 6 PTS ONLY; 4 MTHS OF TD 12 PTS ONLY; 2 MTHS OF TD 19 PTS ONLY.   |                       |                   |  |               |
| 0 WIII3 OF 1D01 13 O   |                       |                   | AVAILABLE FOR QUESTION 8:              |               |
|  | WAXII                 | MUM POINTS        | AVAILABLE FOR QUESTION 8:              | (19113)       |
| TOTAL MAXIMUM POSS   | SIBLE SCORE OF 99.    |                   |  |               |
|  |                       |                   | TOTAL RECLAMATION                      | ON SCORE:     |
| INSPECTIONS:   |                       |                   |  |               |
| Mall 100   | 4 Deil                | لمما              | Canall                                 | Darmit        |
| AAGILLIC   |                       | EU                | Caliceli                               | -епш          |
|  |                       |                   | W                                      |               |
|  | Dani                  | l A. Flac         | n <b>k</b> .                           |               |
| January 13, 2017  DATE RELEASED  | INSPEC                |                   |  |               |
|  |                       |                   |  |               |

