



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
www.dep.wv.gov

September 18, 2015

## FINAL INSPECTION REPORT

### Fracture Permit Cancelled

DOMINION EXPLORATION & PRODUCTION,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-3303176, issued to DOMINION EXPLORATION & PRODUCTION, and listed below has been received in this office. The permit has been cancelled as of 9/16/2015.

A handwritten signature in blue ink, appearing to read 'James Martin', is positioned above the printed name.

James Martin  
Chief

Operator: DOMINION EXPLORATION & PRODUCTIO  
Operator's Well No: 1  
Farm Name: RIGHTMIRE, H.  
**API Well Number: 47-3303176**  
Date Issued: 04/07/2010

Date Cancelled: 09/16/2015

Promoting a healthy environment.

9/18/2015

GPS YES  NO

DATE STARTED/LOCATION:  API #: 47-33-3176 WELL NO. 1  
 DRILLING COMMENCED:  OPERATOR: Consol Gas Company  
 TD DATE:  DEPTH:  FARM: Right mine, H  
 WATER DEPTHS  COAL DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:  
 A. CONSTRUCTION YES  NO  (2 PTS) B. DRILLING YES  NO  (2 PTS) (4 PTS) \_\_\_\_\_  
 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES  NO  (4 PTS) (4 PTS) \_\_\_\_\_  
 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES  NO  (4 PTS) (4 PTS) \_\_\_\_\_

4. CONSTRUCTION:  
 WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?  
 A. ROAD DITCHES 1  2  3  4  (PTS) B. CROSS DRAINS 1  2  3  4  5  (PTS)  
 C. CULVERTS 1  2  3  4  5  (PTS) D. CREEK CROSSINGS 1  2  3  (PTS)  
 E. DIVERSION DITCHES 1  2  3  (PTS) F. BARRIERS 1  2  3  (PTS)  
 G. TEMPORARY SEEDING YES  NO  (10 PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) \_\_\_\_\_  
 5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES  NO  (2 PTS) (2 PTS) \_\_\_\_\_  
 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES  NO  (9 PTS) (9 PTS) \_\_\_\_\_

7. RECLAMATION:  
 A. ROADWAY 1  2  3  (PTS) B. LOCATION 1  2  3  (PTS)  
 C. PITS 1  2  3  (PTS) D. PIPELINES 1  2  3  (PTS)  
 E. TANK DIKES 1  2  3  (PTS) F. API INSTALLED YES  NO  (3 PTS)  
 G. ADEQUATE SEEDING MATERIALS 1  2  3  (PTS)  
 H. WAS SEED BED ADEQUATE 1  2  3  (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) \_\_\_\_\_

8. WAS RECLAMATION COMPLETED WITHIN:  
 6 MTHS OF TD \_\_\_ 6 PTS ONLY; 4 MTHS OF TD \_\_\_ 12 PTS ONLY; 2 MTHS OF TD \_\_\_ 19 PTS ONLY.  
 MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) \_\_\_\_\_

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: \_\_\_\_\_

INSPECTIONS:

Cancel

Received

SEP 17 2015

9/16/15  
DATE RELEASED

S. D. Waratt  
INSPECTOR

Office of Oil and Gas  
WV Dept. of Environmental Protection

9/18/2015