

INSPECTORS REPORT

Operator: Enervest Operating Company, LLC.

API Number: 47-033-03566 Douglas #2

Findings:

RIH to tag cement and prepare to cut and pull casing. No problems were found during this inspection.

Does this inspection identify any dust issues? Yes No. If Yes, explain.

Sam Ward

Oil & Gas Inspector

12/18/2019

Date