PAGE 1

GPS YES [] NO [X]

PAGE 1			100.00		1)
DATE STARTED/LOCATION:	Cancel Not Drilled	API#:	47-033-05825	WELL NO.	KST3BHS
DRILLING COMMENCED:					
TD DATE: WATER DEPTHS QUESTIONS FOR THIS REPOR AND REGULATIONS 35CSR 4-	DEPTH: T ARE IN ACCORDA 12.1 AND 35CSR 4-16	NCE OF WV CC	AL DEPTHS DDE 22-6-30	as, William R, a	
POINTS ARE TO BE GIVEN U	JP TO MAXIMUM A	S SHOWN BASI	ED ON PERFOR	MANCE.	
1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING: A. CONSTRUCTION YES [] NO [] (2_ PTS) B. DRILLING YES [] NO [] (2_ PTS)					(4 PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [] NO [] (4_PTS)					(4 PTS)
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_PTS)					(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SED A. ROAD DITCHES (1)_(2)_(3)_(4) C. CULVERTS (1)_(2)_(3)_(4) E. DIVERSION DITCHES (1)_ G. TEMPORARY SEEDING Y	3)_(4)_ (PTS))_(5)_(PTS). (2)_(3)_(PTS)	B. CROSS DE D. CREEK CE F. BARRIERS	RAINS (1)_(2)_(. ROSSINGS (1)_(S (1) (2) (3) (P	(3)_(4)_ (5)_(P1 (2)_(3)_ (PTS) (TS)	5)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [] NO [] (2_PTS)					(2 PTS)
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES[] NO[] (9_PTS)					(9 PTS)
7. RECLAMATION: A. ROADWAY (1)_(2)_(3)_(I C. PITS (1)_(2)_(3)_(PTS) E. TANK DIKES (1)_(2)_(3)_ G. ADEQUATE SEEDING MATH. WAS SEED BED ADEQUATE 8. WAS RECLAMATION COMES OF TD 6_PTS ON	TERIALS (1)_(2)_(3) TE (1)_(2)_(3)_(PTS))_(F15)) POINTS	AVAILABLE FO	R QUESTION	
6 MIHS OF ID 6_FISON	MAXI	MUM POINTS	AVAILABLE FO	R QUESTION	8: (19 PTS)
TOTAL MAXIMUM POS	SIBLE SCORE OF 99	9.	тота	L RECLAMA	TION SCORE:
INSPECTIONS :	ancel Not Drilled				
11/2/2019 DATE RELEASED	INSPE	ECTOR When	with		