

west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

March 07, 2016

FINAL INSPECTION REPORT

New Well Permit Cancelled

HARD ROCK EXPLORATION, INC.,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-3502981, issued to HARD ROCK EXPLORATION, INC., and listed below has been received in this office. The permit has been cancelled as of 3/1/2016.

James Martin Chief

Operator: HARD ROCK EXPLORATION, INC.

Operator's Well No: HR 367


Farm Name: HALL, JON G. & VICKI JO

API Well Number: 47-3502981

Date Issued: 09/09/2010

Date Cancelled: 03/01/2016

Promoting a healthy environment.



INSPECTORS PERMIT SUMMARY FORM

		GPS YES [] NO []		
DA	TE STARTED/LOCATION: Never Drilled	OPERATOR:	HARD ROCK EXPLORA	ATION, INC.
DRILLING COMMENCED:		FARM:	HALL, JON G. & VICKI JO	
TO DATE: DEPTHS:		Well No:	HR 367	
WA	TER DEPTHS:	COAL DEPTHS	IS	
	JESTIONS FOR THIS REPORT ARE IN ACCORDANC 2.1 AND 35CSR 4-16 AND THE GENERAL WATER PO			NS 35CSR
PC	DINTS ARE TO BE GIVEN UP TO MAXIMUM AS S	HOWN BASED O	N PERFORMANCE.	
1.	Constant Constant Management Constant C	CTOR BEFORE T NO[] (2_PTS NO[] (2_PTS	5)	(4_PTS)
2.	WAS THE TIMBER CUT, STACKED, AND BRUSH UBEFORE DIRT WORK STARTED? YES [JSED FOR SEDIM] NO [] (2_PT		(4_PTS)
3.	ARE ALL LOCATION AND/OR ROAD BANKS BEIN	IG SLOPED? YES	S[] NO[] (4_PTS)	(4_PTS)
4.	CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS) C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) D. CREEK CROSSINGS (1)_(2)_(3)_(PTS) E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS) G. TEMPORARY SEEDING YES[] NO[] (10_PTS)			
	PO	OINTS AVAILABL	E FOR QUESTION 4:	(33_PTS)
5.	HAS TOP SOIL (IF ANY) BEEN STOCKED PILED?	YES[]	NO [] (2_PTS)	(2_PTS)
6.	IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [] NO [] (9_PTS) (9_PTS)—			
7.	C. PITS (1)_(2)_(3)_(PTS) E. TANK DIKES (1)_(2)_(3)_(PTS) G. ADEQUATE SEEDING MATERIALS (1)_(2)_ H. WAS SEED BED ADEQUATE (1)_(2)_	(3)_(PTS)	(1)_(2)_(3)_(PTS (1)_(2)_(3)_(PTS LED YES[] NO[S)
8.	WAS RECLAMATION COMPLETED WITHIN: 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY; POINTS AVAILABLE FOR QUESTION 8: (19_PTS)			
TOTAL MAXIMUM POSSIBLE SCORE OF 99. TOTAL RECLAMATION SCORE:				
	3 1 2016 Concelled	Jacqual	in Shortan SPECTOR'S SIGNATURE	