

west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

October 13, 2015

FINAL INSPECTION REPORT

New Well Permit Cancelled

WACO OIL & GAS CO INC,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-4901762, issued to WACO OIL & GAS CO INC, and listed below has been received in this office. The permit has been cancelled as of 10/6/2015.

James Martin Chief

Operator: WACO OIL & GAS CO INC

Operator's Well No: MALNICK 1785

Farm Name: MALNICK, STEVE & JENNIFER

API Well Number: 47-4901762

Date Issued: 06/29/2006

Date Cancelled: 10/06/2015

Promoting a healthy environment.

INSPECTORS PERMIT SUMMARY FORM

GPS YES | NO []

DATE STARTED/LOCATION:			OPERATOR:	WACO OIL & GAS CO INC		
DRILLING COMMENCED:			FARM:	MALNICK, STEVE & JENNIFER		
TO DATE: DEPTHS:			Well No:	MALNICK 1785		
WATER DEPTHS:			COAL DEPTHS	is		
QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.						
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.						
I.	DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:					
	A. CONSTRUCTION	YES[]	NO[] (2_PTS))	(4_PTS)	
	B. DRILLING	YES[]	NO[] (2_PTS)			
2.	WAS THE TIMBER CUT, STACKED, AND BEFORE DIRT WORK STARTED?		SED FOR SEDIMI NO [] (2_PT:		(4_PTS)	
3.	ARE ALL LOCATION AND/OR ROAD BA	NKS BEING	SLOPED? YES	[] NO[] (4_PTS)	(4_PTS)	
4. CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? A. ROAD DITCHES (1)_(2)_(3)_(4)_(7TS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS) C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) D. CREEK CROSSINGS (1)_(2)_(3)_(PTS) E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS) G. TEMPORARY SEEDING YES[] NO[] (10_PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS)						
5.	HAS TORSON (IF ANY) PERM STOCKER			-	(33_PTS)	
	HAS TOP SOIL (IF ANY) BEEN STOCKED		• •	NO[] (2_PTS)	(2_PTS)	
5. -	IS THE PIT PROPERLY INSTALLED AND	MAINTAIN	IED? YES[] I	NO[] (9PTS)	(9_PTS)	
7.	RECLAMATION: A. ROADWAY (1)_(2)_(3)_(PTS) C. PITS (1)_(2)_(3)_(PTS) E. TANK DIKES (1)_(2)_(3)_(PTS) G. ADEQUATE SEEDING MATERIALS H. WAS SEED BED ADEQUATE) E) F (1)_(2)_(3 (1)_(2)_(3)_(PTS)	., .	S)] (3_PTS)	
POINTS AVAILABLE FOR QUESTION 7: (24_PTS)					(24_PTS)	
B. WAS RECLAMATION COMPLETED WITHIN: 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY; POINTS AVAILABLE FOR QUESTION 8: (19_PTS) TOTAL MAXIMUM POSSIBLE SECRECE VECTOR VECTOR AND TOTAL RECLAMATION SCORE:						
	DATE RELEASED OCT	9 2 015		pector's signature	IF.	

Office of Oil and Gas RECORD INSPERCIEIONS A CONFISTWELL ON PAGE 2