DATE RELEASED

INSPECTORS PERMIT SUMMARY FORM

PAGE 1	GPS YES NO X	
DATE STARTED/LOCATION: Conce	API#: WELL NO.	T. 0 ev
DRILLING COMMENCED:	OPEDATOR	eun B6H
TD DATE:	DEPTH: FARM: XTO Energy.	Tuc
	COAL DEPTHS ATO CHECKE	<i></i>
WATER DEPTHS QUESTIONS FOR THIS REPORT ARE IN AC AND REGULATIONS 35CSR 4-12.1 AND 350	CCORDANCE OF WV CODE 22-6-30 CSR 4-16 AND THE GENERAL WATER POLLUTION CONT	ROL PERMIT
1. DID OPERATOR GIVE PROPER NOTICE	MUM AS SHOWN BASED ON PERFORMANCE. TO INSPECTOR BEFORE THE FOLLOWING: PTS) B. DRILLING YES NO (2 PTS)	
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4 PTS)		(4 PTS)(4 PTS)
3. ARE ALL LOCATION AND/OR ROAD BA	ANKS BEING SLOPED? YES NO (4 PTS)	(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONT	TROL STRUCTURES PROPERLY INSTALLED/MAINTAINE	ED?
A. ROAD DITCHES 1234(P'	TS) B. CROSS DRAINS 12_3_45_	(PTS)
C. CULVERTS 12345(P	TS) D. CREEK CROSSINGS 123(PTS	S)
E. DIVERSION DITCHES 1 2 3 (P	TS) F. BARRIERS 123(PTS)	
G. TEMPORARY SEEDING YES NO _	(10 PTS) POINTS AVAILABLE FOR QUESTION 4:	(33 PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED	PILED? YES NO (2 PTS)	(2 PTS)
6. IS THE PIT PROPERLY INSTALLED AND	MAINTAINED? YES NO (9 PTS)	(9 PTS)
7. RECLAMATION:		
A. ROADWAY 123(PTS)	B. LOCATION 123(PTS)	
C. PITS 123(PTS)	D. PIPELINES 123(PTS)	
(Voruntaria) ii protestinia in protestinia ii ii ii ii	F. API INSTALLED YESNO(3 PTS)	
G. ADEQUATE SEEDING MATERIALS 1_	_23(PTS)	
H. WAS SEED BED ADEQUATE 123	(PTS) POINTS AVAILABLE FOR QUESTION 7:	(24 PTS)
8. WAS RECLAMATION COMPLETED WIT A. CONVENTIONAL:	HIN:	
6 MTHS OF TD6 PTS ONLY;	4 MTHS OF TD12 PTS ONLY; 2 MTHS OF TD	_19 PTS ONLY.
B. HORIZONTAL:		
3 YRS OF PAD COMPLETION 5 YRS OF PAD COMPLETION	19 PTS ONLY; 4 YRS OF PAD COMPLETION 16 PT 13 PTS ONLY	S ONLY;
	MAXIMUM POINTS AVAILABLE FOR QUESTION 8:	(19 PTS)
TOTAL MAXIMUM POSSIBLE SCOR		
	TOTAL RECLAMATION	N SCORE:
Cancel	1D War FR	
5/13/2020	14 11/2 - FR	

INSPECTOR