PAGE 1

GPS YES NO	
DATE STARTED/LOCATION: API #: WELL NO	
DRILLING COMMENCED: COMPOSITION COMPOSITION SIGNS	
TO DATE.	
DEPTH: FARM: Fornick, Walter & Boulah COAL DEPTHS	
WATER DEPTHS	
QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30	
AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT	
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.	
TO DE CITATION OF LEGISLATION OF LOTTING BOLD ON THE POLICY OF THE POLIC	
A. CONSTRUCTION YES NO (2 PTS) B. DRILLING YES NO (2 PTS)	
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE (4 PTS) (4 PTS)	-
DIRT WORK STARTED? YES NO (4 PTS) (4 PTS)	_
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4 PTS) (4 PTS)	
4. CONSTRUCTION: (4 PTS) (4 PTS)	-
WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?	
A DOAD DITOUTE 1	
A. ROAD DITCHES 1 2 3 4 (PTS) B. CROSS DRAINS 1 2 3 4 5 (PTS) C. CULVERTS 1 2 3 4 5 (PTS) D. CREEK CROSSINGS 1 2 3 (PTS)	
E. DIVERSION DITCHES 1 2 3 (PTS) F. BARRIERS 1 2 3 (PTS)	
G. TEMPORARY SEEDING YES NO. (10 DTS) DOINTS ANALY AND THE TOTAL T	
	_
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO(2 PTS) (2 PTS)	
5. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9 PTS) (9 PTS)	
	-
7. RECLAMATION:	
A. ROADWAY 123(PTS) B. LOCATION 123(PTS)	
C. PITS 1 2 3 (PTS) D. PIPELINES 1 2 3 (PTS)	
E. TANK DIKES 1 2 3 (PTS) F. API INSTALLED YES NO (3 PTS)	
G. ADEQUATE SEEDING MATERIALS 123(PTS)	
I. WAS SEED BED ADEQUATE 1 2 3 (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS)	
B. WAS RECLAMATION COMPLETED WITHIN:	
A. CONVENTIONAL:	
6 MTHS OF TD6 PTS ONLY; 4 MTHS OF TD12 PTS ONLY; 2 MTHS OF TD19 PTS ONLY.	
B. HORIZONTAL:	
3 YRS OF PAD COMPLETION 19 PTS ONLY; 4 YRS OF PAD COMPLETION 16 PTS ONLY; 13 PTS ONLY;	
5 YRS OF PAD COMPLETION 13 PTS ONLY	
MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS)	
TOTAL MAXIMUM POSSIBLE SCORE OF 99.	i
TOTAL RECLAMATION SCORE:	_
Canical Constant	
5/19/2020 DATE RELEASED INSPECTOR	
THE DOLON	