DATE RELEASED

Caucel INSPECTORS PERMIT SUMMARY FORM

PAGE 1	GPS Y	YES NO X	901
DATE STARTED/LOCATION:	. API #-	WELLNO	
DRILLING COMMENCED:	uce 47-049-024	60	Edwin Bunner MRN 1A
TD DATE:	DWN Pri	oduction Com	yany, LEC
WATER DEPTHS QUESTIONS FOR THIS REPORT ARE	COAL DEPTHS COAL D	un L. Bunner	+ Sandra J. Bunn
AND REGULATIONS 35CSR 4-12.1 AN	D 35CSR 4-16 AND THE GENERAL WATER	POLLUTION CO	NTROL PERMIT
POINTS ARE TO BE GIVEN UP TO M 1. DID OPERATOR GIVE PROPER NO A. CONSTRUCTION YES NO	IAXIMUM AS SHOWN BASED ON PERFORMICE TO INSPECTOR BEFORE THE FOLLOW (2 PTS) B. DRILLING YES NO	RMANCE. WING: (2 PTS)	(4 PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4 PTS)			(4 PTS)
3. ARE ALL LOCATION AND/OR ROA	D BANKS BEING SLOPED? YES NO _	(4 PTS)	(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT (CONTROL STRUCTURES PROPERLY INSTA	ALLED/MAINTAI	NED?
A. ROAD DITCHES 1234_	(PTS) B. CROSS DRAINS 1	2 3 4 5	5 (PTS)
C. CULVERTS 12345_	_ (PTS) D. CREEK CROSSINGS	123 (F	PTS)
E. DIVERSION DITCHES 123_	(PTS) F. BARRIERS 12	3(PTS)	
G. TEMPORARY SEEDING YES 1	NO (10 PTS) POINTS AVAILABLE FO	OR QUESTION 4	: (33 PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOC	EKED PILED? YES NO (2 PTS)		(2 PTS)
6. IS THE PIT PROPERLY INSTALLED	AND MAINTAINED? YES NO (9 I	PTS)	(9 PTS)
7. RECLAMATION:			
A. ROADWAY 123(PTS)	B. LOCATION 123(PTS))	
	D. PIPELINES 1 2 3 (PTS)		
E. TANK DIKES 123(PTS)	F. API INSTALLED YESNO((3 PTS)	
G. ADEQUATE SEEDING MATERIALS			
H. WAS SEED BED ADEQUATE 12_	3(PTS) POINTS AVAILABLE FO	R QUESTION 7:	(24 PTS)
8. WAS RECLAMATION COMPLETED A. CONVENTIONAL:	WITHIN:		*
6 MTHS OF TD6 PTS ONL	Y; 4 MTHS OF TD12 PTS ONLY;	2 MTHS OF TD	19 PTS ONLY
B. HORIZONTAL:			DTID ONDI.
3 YRS OF PAD COMPLETION _ 5 YRS OF PAD COMPLETION _	19 PTS ONLY; 4 YRS OF PAD COMPLE 13 PTS ONLY	ETION 16 P	TS ONLY;
TOTAL MAXIMUM POSSIBLE SO	MAXIMUM POINTS AVAILABLE FOI	R QUESTION 8:	(19 PTS)
		L RECLAMATIC	ON SCORE:
Cancel			
5/18/2020	20 Wardt		

INSPECTOR