Form IR-11A

Rev. 8/21/2013

State of West Virginia
Office of Oil and Gas

INSPECTORS REPORT

Operator: Consolidation Coal Company

API Number: 51-00344, well number 4527

Findings:

Well has been plugged and proper monument is in place. Reclamation nearly complete but a few areas that received additional grading now need to be seeded and mulched. Silt fence still in place.

Does this inspection identify any dust issues? ☐ **Yes** ☒ **No.** **If Yes, explain.**

Oil & Gas Inspector

10/17/2016

Date