

INSPECTORS REPORT

Operator: GasStar

API Number: 47-051-01592 Goudy 4 H

Findings:

Set 20 inch conductor to 110 ft. Pumped cement down , let set, then grouted to surface

Used 187 sx of cmnt

Location looks clean. E & S effective and site is vegetating.



Oil & Gas Inspector

1/1/2013

Date