

STATE OF WEST VIRGINIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

Farm name: Alawest, Incorporated Operator Well No.: 026502

LOCATION: Elevation: 2157' Quadrangle: Davy  
District: Big Creek County: McDowell  
Latitude: 43 Feet South of 59 Deg. 66 Min. 51 Sec.  
Longitude: 41 Feet West of 39 Deg. 408 Min. 9 Sec.

Well Type: OIL \_\_\_\_\_ GAS X

Company Diversified Producon, LLC Coal Operator Alawest, Inc  
PO Box 6070 or Owner PO Box 920  
Charleston, WV 25362 Welch, WV 24801  
Coal Operator \_\_\_\_\_  
Agent Jeff Mast or Owner \_\_\_\_\_  
Permit Issued Date 3-19-21

AFFIDAVIT

STATE OF ~~WEST VIRGINIA~~, KY  
County of Floyd ss:

Rodney Osborne and Estill Johnson being first duly sworn according to law depose and say that they are experienced in the work of plugging and filling oil and gas wells and were employed by the above named well operator, and participated in the work of plugging and filling the above well say that said work was commenced on the 21 day of April, 2021, and the well was plugged and filled in the following manner:

| TYPE                      | FROM  | TO      | PIPE REMOVED | LEFT                |
|---------------------------|-------|---------|--------------|---------------------|
| 155 sks of Class A Cement | 1864' | Surface |              | 60' of 9 5/8"       |
|                           |       |         |              | 299' of 7" CTS      |
|                           |       |         |              | 1987' of 4 1/2" CTS |
|                           |       |         |              |                     |
|                           |       |         |              |                     |
|                           |       |         |              |                     |

Description of monument: 7" casing w/ API # 36" above ground and that the work of plugging and filling said well was completed on the 22 day of April, 2021.

And further deponents saith not. [Signature]  
Estill Johnson

Sworn and subscribe before me this 23 day of April, 2021

My commission expires: 2/4/2022

Stella M Slove  
Notary Public



Affidavit reviewed by the Office of Oil and Gas: [Signature] Title: Inspector

05/07/2021

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED 4/21/21  
PLUGGING COMPLETED 4/22/21  
VERBAL PERMISSION ON \_\_\_\_\_

OPERATOR: Diversified  
FARM: Alawest, Inc.  
WELL NO: \_\_\_\_\_

- 1. IS COAL BEING MINED IN THE AREA? YES NO N/A
- 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
  - A. BOTTOM HOLE PLUGGED YES NO N/A
  - B. 100' PLUGS YES NO N/A
  - C. LATEX PLUGS USED FOR H<sub>2</sub>S GAS YES NO N/A
  - D. PROPER PLUGS THROUGH COAL SEAMS YES NO N/A
  - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES NO N/A
  - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A

| TYPE                  | FROM         | TO             | PIPE REMOVED |
|-----------------------|--------------|----------------|--------------|
| <u>Class A Cement</u> | <u>1864'</u> | <u>surface</u> |              |
|                       |              |                |              |
|                       |              |                |              |
|                       |              |                |              |
|                       |              |                |              |
|                       |              |                |              |
|                       |              |                |              |
|                       |              |                |              |
|                       |              |                |              |
|                       |              |                |              |

- 3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NO
- 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES NO
- 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NO
- 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
- 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NO
- 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?
 

|                                 |  |
|---------------------------------|--|
| A. RECLAIMED <u>YES</u> NO      | B. FENCES REPLACED <u>YES</u> NO       |
| C. MULCHED <u>YES</u> NO        | D. PROPER DRAINAGE <u>YES</u> NO       |
| E. SEEDED <u>YES</u> NO         | F. ALL EQUIPMENT REMOVED <u>YES</u> NO |
| G. PIT BACKFILLED <u>YES</u> NO |  |

4/22/21  
DATE RELEASED

[Signature]  
INSPECTOR'S SIGNATURE

RECORD ALL VISITS TO THIS WELL ON PAGE 2