API NO.: 47-059-00569-00-00

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED	OPERATOR: CORE APPALACHIA OPERATIN	IG LLC	
PLUGGING COMPLETED	FARM: COTIGA DEV. CO.		
VERBAL PERMISSION ON	WELL NO: 808647		
1. IS COAL BEING MINED IN THE AREA?	YES	NO	N/A
2. WERE CEMENT AND GEL MIXED AND US STANDARDS?	SED IN ACCORDANCE WITH ACCEPTED IN	NDUSTF	RY
A. BOTTOM HOLE PLUGGED	YES	NO	N/A
B. 100' PLUGS	YES	NO	N/A
C. LATEX PLUGS USED FOR	H ₂ S GAS YES	NO	N/A
D. PROPER PLUGS THROUGH		NO	N/A
E. PROPER PLUGS SET TO P	PROTECT FRESHWATER YES NO	N/A	
F. PROPER AMOUNT OF GEL	USED TO DISPLACE PLUGS YES NO	N/A	
TYPE FROM	TO PIPH	E REMO	OVED
			
: 			
	_/		
	t Vaconto		
3. WERE ALL CHANGES APPROVED BY INS	SPECTOR?	YES	NO
4. WAS THE EQUIPMENT USED FOR PULLI			
AND RIGGED TO PULL 150% OF THE H	HEAVIEST STRING OF PIPE EXPECTED		
TO BE PULLED?		YES	NO
5. DID THE OPERATOR GIVE THE INSPEC	TOR PROPER NOTICE?	YES	NO
C LIBBE ACCUDANT DI HOCTMO DECORDO I	VEDE DV EUE ODEDAHOD?	VTC	NO
6. WERE ACCURATE PLUGGING RECORDS K	EPT BY THE OPERATOR?	YES	NO
7 LING A DOODED MONITARING CERT LITTEL A	ביתווא ביים משתא ביים	YES	NO
7. WAS A PROPER MONUMENT SET WITH A	PI NUMBER ATTACHED:	IES	INO
8. DID WELL SITE AND ACCESS ROAD ME	FT THE FOLLOWING RECLAMATION		
REQUIREMENTS?	EI THE POLLOWING RECLAMATION		
A. RECLAIMED YES NO	B. FENCES REPLACED	YES	NO
C. MULCHED YES NO	D. PROPER DRAINAGE	YES	NO
E. SEEDED YES NO	F. ALL EQUIPMENT REMOVED	YES	NO
G. PIT BACKFILLED YES NO	1. THE EQUITION REPOVED	باند	-10
1 2 2			
471	Wan Will		
DATE RELEASED	INSPECTOR'S SIGNATURE		

RECORD ALL VISITS TO THIS WELL ON PAGE 2