IR-8
(REV 4-99)

API NO.: 47-061-00507

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED_____
PLUGGING COMPLETED_____
VERBAL PERMISSION ON_____

OPERATOR: Northeast Natural Energy
FARM: Moore & Eddy
WELL NO: 6

1. IS COAL BEING MINED IN THE AREA? YES NO ✓ N/A

2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
   - A. BOTTOM HOLE PLUGGED YES ✓ NO N/A
   - B. 100' PLUGS YES ✓ NO N/A
   - C. LATEX PLUGS USED FOR H_2S GAS YES NO N/A ✓
   - D. PROPER PLUGS THROUGH COAL SEAMS YES ✓ NO N/A
   - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES ✓ NO N/A
   - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES ✓ NO N/A

TYPE	FROM	TO	PIPE REMOVED

3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES ✓ NO

4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES ✓ NO

5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES ✓ NO

6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES ✓ NO

7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES ✓ NO

8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?
   - A. RECLAIMED YES ✓ NO
   - B. FENCES REPLACED YES ✓ NO
   - C. MULCHED YES ✓ NO
   - D. PROPER DRAINAGE YES ✓ NO
   - E. SEEDED YES ✓ NO
   - F. ALL EQUIPMENT REMOVED YES ✓ NO
   - G. PIT BACKFILLED YES ✓ NO

Gayne Knitowski
Digitally signed by Gayne Knitowski
Date: 2020.05.19 12:23:13 -04'00'

5-19-2020
DATE RELEASED

INSPECTOR'S SIGNATURE

RECORD ALL VISITS TO THIS WELL ON PAGE 2

IR-8
PAGE 2
API NO: 47-061-00507

DATE	VISITS