



west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

March 24, 2014

FINAL INSPECTION REPORT

Horizontal Well Permit Cancelled

CHESAPEAKE APPALACHIA, L.L.C.,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-6900097, issued to CHESAPEAKE APPALACHIA, L.L.C., and listed below has been received in this office. The permit has been cancelled as of 3/14/2014.

James Martin Chief

Operator: CHESAPEAKE APPALACHIA, L.L.C.

Operator's Well No: S.E.W. TRUST OHI 3H

Farm Name: WOLOSHAN, SHANE - TRUSTEE

API Well Number: 47-6900097Date Issued: 10/20/2011

Date Cancelled: 03/14/2014

Promoting a healthy environment.

INSPECTORS PERMIT SUMMARY FORM

	GPS YES []	NO []
DATE STARTED/LOCATION:	OPERATOR:	CHESAPEAKE APPALACHIA, L.L.C.
DRILLING COMMENCED:	FARM:	WOLOSHAN, SHANE - TRUSTEE
TO DATE: DEPTHS:	Well No:	S.E.W. TRUST OHI 3H
WATER DEPTHS:		
QUESTIONS FOR THIS REPORT ARE IN ACCORD. 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATE	ER POLLUTION	CONTROL PERMIT.
POINTS ARE TO BE GIVEN UP TO MAXIMUM A		
I. DID OPERATOR GIVE PROPER NOTICE TO IN A. CONSTRUCTION YES[] NO[B. DRILLING YES[] NO[] (2_PTS)	
2. WAS THE TIMBER CUT, STACKED, AND BRU BEFORE DIRT WORK STARTED?		
YES [] NO	[] (2_PTS)	(4_PTS)
3. ARE ALL LOCATION AND/OR ROAD BANKS	BEING SLOPED	
YES[] NO[] (4_PTS)	(4_PTS)
4. CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTRO	OL STRUCTURE	S PROPERLY INSTALLED/MAINTAINED?
A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) G. TEMPORARY SEEDING YES[] NO[] (1)	D. CREEK CF F. BARRIER: 10_PTS)	ROSSINGS (1)_(2)_(3)_(PTS) S (1)_(2)_(3)_(PTS)
POINTS AVAILAE	BLE FOR QUES	ΠΟΝ 4: (33_PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILI	ED?YES[] N	O[](2_PTS) (2_PTS)
6. IS THE PIT PROPERLY INSTALLED AND MAI	NTAINED?	
	YES[] NO[] (9_PTS) (9_PTS)
7. RECLAMATION:		
A. ROADWAY (1)_(2)_(3)_(PTS) B. L		(1)_(2)_(3)_(PTS)
C. PITS (1)_(2)_(3)_(PTS) D. P		(1)_(2)_(3)_(PTS)
E. TANK DIKES (1)_(2)_(3)_(PTS) F. A		YES[] NO (3_PTS)
G. ADEQUATE SEEDING MATERIALS (1) (2)		
,)_(3)_(PTS)	PION 5. (24 PES)
POINTS AVAILAE	SLE FOR QUES.	ΠΟΝ 7: (24_PTS)
8. WAS RECLAMATION COMPLETED WITHIN:		
6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF		_
POINTS AVAILAE	3LE FOR QUEST	ΓΙΟΝ 8: (19_PTS)
TOTAL MAXIMUM POSSIBLE SCORE OF 99.		
ТО	TAL RECLAMA	TION SCORE:
3 14 LOIY DATE RELEASED	TNSPECTOR'	S SIGNATURE
Can CILLA RECORD INSPECTIONS TO THIS	S WELL ON PAC	GE 2