



west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

March 24, 2014

FINAL INSPECTION REPORT

Horizontal Well Permit Cancelled

CHESAPEAKE APPALACHIA, L.L.C.,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-6900098, issued to CHESAPEAKE APPALACHIA, L.L.C., and listed below has been received in this office. The permit has been cancelled as of 3/14/2014.

James Martin Chief

Operator: CHESAPEAKE APPALACHIA, L.L.C.

Operator's Well No: S.E.W. TRUST OHI 8H

Farm Name: WOLOSHAN, SHANE - TRUSTEE

API Well Number: 47-6900098Date Issued: 10/20/2011

Date Cancelled: 03/14/2014

Promoting a healthy environment.

INSPECTORS PERMIT SUMMARY FORM

	GPS YES 1	NO[]
DATE STARTED/LOCATION:	OPERATOR:	CHESAPEAKE APPALACHIA, L.L.C.
DRILLING COMMENCED:	FARM:	WOLOSHAN, SHANE - TRUSTEE
TO DATE: DEPTHS:	Well No:	S.E.W. TRUST OHI 8H
WATER DEPTHS:		
QUESTIONS FOR THIS REPORT ARE IN ACCOR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WA	TER POLLUTION	CONTROL PERMIT.
POINTS ARE TO BE GIVEN UP TO MAXIMUM		
1. DID OPERATOR GIVE PROPER NOTICE TO A. CONSTRUCTION YES [] NO B. DRILLING YES [] NO [[] (2_PTS)	
2. WAS THE TIMBER CUT, STACKED, AND BR BEFORE DIRT WORK STARTED?		
YES [] NO	[] (2_PTS)	(4_PTS)
3. ARE ALL LOCATION AND/OR ROAD BANKS	S BEING SLOPED	?
YES[] NO[] (4_PTS)	(4_PTS)
4. CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONT	ROL STRUCTURE	ES PROPERLY INSTALLED/MAINTAINED?
A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) G. TEMPORARY SEEDING YES[] NO[] POINTS AVAILABLE	D. CREEK C F. BARRIER (10_PTS)	ROSSINGS (1)_(2)_(3)_(PTS) LS (1)_(2)_(3)_(PTS) TION 4: (33_PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PI	LED?YES[] N	IO[] (2_PTS) (2_PTS)
6. IS THE PIT PROPERLY INSTALLED AND MA	AINTAINED?	
	YES[] NO[] (9_PTS) (9_PTS)
7. RECLAMATION:		
A. ROADWAY (1)_(2)_(3)_(PTS) B. C. PITS (1)_(2)_(3)_(PTS) D. E. TANK DIKES (1)_(2)_(3)_(PTS) F. G. ADEQUATE SEEDING MATERIALS (1)_(H. WAS SEED BED ADEQUATE (1)_(1)_(1)_(1)_(1)_(1)_(1)_(1)_(1)_(1)_	PIPELINES API INSTALLED	(1)_(2)_(3)_(PTS) (1)_(2)_(3)_(PTS) YES[] NO (3_PTS)
POINTS AVAILA	ABLE FOR QUES	STION 7: (24_PTS)
TOTAL MAXIMUM POSSIBLE SCORE OF 9	F TD 12_PTS ONI ABLE FOR QUES	TION 8: (19_PTS)
DATE RELEASED Canallal	INSPECTOR	SSIGNATURE

RECORD INSPECTIONS TO THIS WELL ON PAGE 2