PAGE 1			GPS YES NO)
DATE STARTED/LOCATION:		API#:	830/249 WELL	vo. 513106
DRILLING COMMENCED:		OPERATOR:	EQT PRODUC	
TD DATE:	DEPTH:			Forest Resources
WATER DEPTHS QUESTIONS FOR THIS REPORT AND REGULATIONS 35CSR 4-1		NCE OF WV CO		N CONTROL PERMIT
POINTS ARE TO BE GIVEN U	P TO MAXIMUM AS	S SHOWN BASI	ED ON PERFORMANCE.	
1. DID OPERATOR GIVE PROPE A. CONSTRUCTION YES 2. WAS THE TIMBER CUT, STADIRT WORK STARTED? YE	NO (2 PTS) ACKED, AND BRUSH	B. DRILLING I USED FOR SE	G YES NO(2 PTS)	(4 PTS) RE (4 PTS)
3. ARE ALL LOCATION AND/C	OR ROAD BANKS BE	ING SLOPED?	YES NO (4 PTS)	(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDI	MENT CONTROL ST	RUCTURES PR	OPERLY INSTALLED/MAI	NTAINED?
A. ROAD DITCHES 123	34(PTS)	B. CROS	S DRAINS 123	45(PTS)
C. CULVERTS 123	45(PTS)	D. CREEK	K CROSSINGS 123	(PTS)
E. DIVERSION DITCHES 1	23(PTS)	F. BARR	IERS 123(PTS)	
G. TEMPORARY SEEDING YE	S NO (10 PT	S) POINTS	AVAILABLE FOR QUEST	ION 4: (33 PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO (2 PTS)				(2 PTS)
6. IS THE PIT PROPERLY INSTA	ALLED AND MAINT	AINED? YES_	NO (9 PTS)	(9 PTS)
7. RECLAMATION:		2.4		
A. ROADWAY 123	(PTS) B. LC	OCATION 1	23(PTS)	
C. PITS 123(PTS)	D. PII	PELINES 1	23(PTS)	
E. TANK DIKES 123	_(PTS) F. AP	I INSTALLED	YESNO(3 PTS)	
G. ADEQUATE SEEDING MATE	ERIALS 123	(PTS)		
H. WAS SEED BED ADEQUATE	123(PTS) POINTS	AVAILABLE FOR QUESTI	ON 7: (24 PTS)
8. WAS RECLAMATION COMP.	LETED WITHIN:			
A. CONVENTIONAL:				
6 MTHS OF TD6 P	TS ONLY; 4 MTH	S OF TD12	2 PTS ONLY; 2 MTHS O	F TD19 PTS ONLY.
B. HORIZONTAL:				
3 YRS OF PAD COMPLI 5 YRS OF PAD COMPLI	ETION 19 PTS ETION 13 PTS	ONLY; 4 YRS ONLY	OF PAD COMPLETION	16 PTS ONLY;
	MAXIN	IUM POINTS A	AVAILABLE FOR QUESTI	ON 8: (19 PTS)

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

Never Drilled

Cancel

TOTAL RECLAMATION SCORE: NA

Buyen Harin 6-10-19