



---

**west virginia** department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
[www.dep.wv.gov](http://www.dep.wv.gov)

June 15, 2016

**FINAL INSPECTION REPORT**

**Fracture Permit Cancelled**

PRIME OPERATING COMPANY,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-8701676, issued to PRIME OPERATING COMPANY, and listed below has been received in this office. The permit has been cancelled as of 6/15/2016.


James Martin  
Chief

Operator: PRIME OPERATING COMPANY  
Operator's Well No: 15980  
Farm Name: DILLON, WILLIAM R.  
**API Well Number: 47-8701676**  
Date Issued: 07/22/2008

Date Cancelled: 06/15/2016

Promoting a healthy environment.

06/17/2016



LATITUDE  $36^{\circ}47'30''$

LONGITUDE  $81^{\circ}45'30''$

WALTER C. BAILEY  
D.B. 178, P. 249  
T.M. 27, P. 1  
(LEE DIST, CALHOUN CO.)

DAVID E. BOWEN  
D.B. 322, P. 14  
T.M. 31, P. 15

CLYDE MANLEY  
D.B. 437, P. 223  
T.M. 1, P. 2.1

SUE ANN STEBLE  
D.B. 154, P. 609  
T.M. 26, P. 1  
(LEE DISTRICT, CALHOUN CO.)

ORETA CONFORD  
D.B. 135, P. 254  
T.M. 27, P. 45  
(LEE DIST, CALHOUN CO.)

294.8 AC.  
D.B. 307, P. 107  
T.M. 1, P. 4

LARRY D. SPANGLER ET AL  
D.B. 435, P. 168  
T.M. 1, P. 6 THRU 11

JACK L. HARDWAY  
D.B. 292, P. 353  
D.B. 367, P. 745  
T.M. 1, P. 61 & 6.2

FILE NO. \_\_\_\_\_  
DRAWING NO. \_\_\_\_\_  
SCALE  $1'' = 1000'$   
MINIMUM DEGREE OF ACCURACY  $1/4''$   
PROVEN SOURCE OF ELEVATION WELL NO. 1676-P

I THE UNDERSIGNED, HEREBY CERTIFY THAT THIS PLAT IS CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF AND SHOWS ALL THE INFORMATION REQUIRED BY LAW AND THE REGULATIONS ISSUED AND PRESCRIBED BY THE DEPARTMENT OF MINES.  
(SIGNED) William R. Guinn  
R.P.E. \_\_\_\_\_ L.L.S. 801



(+) DENOTES LOCATION OF WELL ON UNITED STATES TOPOGRAPHIC MAPS  
FORM IV-6  
(8-78)



DATE MARCH 08 20 07  
OPERATOR'S WELL NO. 15980  
API WELL NO. \_\_\_\_\_  
47-087-01676F  
STATE COUNTY PERMIT

Division of Environmental Protection  
Office of Oil & Gas

FRAC CANCELLED

WELL TYPE: OIL  GAS  LIQUID INJECTION \_\_\_\_\_ WASTE DISPOSAL \_\_\_\_\_  
(IF "GAS", PRODUCTION  STORAGE \_\_\_\_\_ DEEP \_\_\_\_\_ SHALLOW   
LOCATION: ELEVATION 811.3 WATER SHED ARMY PARK OF HENRY'S PARK  
DISTRICT SMITHFIELD COUNTY RAVE

SURFACE OWNER WILLIAM RICHARD DILLON ACREAGE 244.0 ±  
OIL & GAS ROYALTY OWNER WILLIAM RICHARD DILLON LEASE ACREAGE 258.8  
LEASE NO. \_\_\_\_\_

PROPOSED WORK: DRILL  CONVERT \_\_\_\_\_ DRILL DEEPER \_\_\_\_\_ REDRILL \_\_\_\_\_ FRACTURE OR STIMULATE \_\_\_\_\_ PLUG OFF OLD FORMATION \_\_\_\_\_ PERFORATE NEW FORMATION \_\_\_\_\_ OTHER PHYSICAL CHANGE IN WELL (SPECIFY) \_\_\_\_\_

PLUG AND ABANDON \_\_\_\_\_ CLEAN OUT AND REPLUG \_\_\_\_\_  
TARGET FORMATION BEEMA MAX OF S&W ESTIMATED DEPTH \_\_\_\_\_  
WELL OPERATOR BEEMA MAX OF S&W DESIGNATED AGENT ROBERT L. BLACKBURN  
ADDRESS 211 S. MAIN STREET ADDRESS SAME

COMPLETION BLUEPRINT 037991

06/17/2016

Charleston, WV

INSPECTORS PERMIT SUMMARY FORM

GPS YES [ ] NO [ ]

DATE STARTED/LOCATION: \_\_\_\_\_  
DRILLING COMMENCED: \_\_\_\_\_  
TO DATE: \_\_\_\_\_ DEPTHS: \_\_\_\_\_  
WATER DEPTHS: \_\_\_\_\_

OPERATOR: Prime Operating Camp.  
FARM: William R Dillion  
Well No: 15980  
COAL DEPTHS \_\_\_\_\_

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
- A. CONSTRUCTION YES [ ] NO [ ] (2\_PTS) (4\_PTS) \_\_\_\_\_
  - B. DRILLING YES [ ] NO [ ] (2\_PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [ ] NO [ ] (2\_PTS) (4\_PTS) \_\_\_\_\_
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [ ] NO [ ] (4\_PTS) (4\_PTS) \_\_\_\_\_
4. CONSTRUCTIONS:  
WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
- A. ROAD DITCHES (1)\_ (2)\_ (3)\_ (4)\_ (5)\_ (PTS)
  - B. CROSS DRAINS (1)\_ (2)\_ (3)\_ (4)\_ (5)\_ (PTS)
  - C. CULVERTS (1)\_ (2)\_ (3)\_ (4)\_ (5)\_ (PTS)
  - D. CREEK CROSSINGS (1)\_ (2)\_ (3)\_ (PTS)
  - E. DIVERSION DITCHES (1)\_ (2)\_ (3)\_ (PTS)
  - F. BARRIERS (1)\_ (2)\_ (3)\_ (PTS)
  - G. TEMPORARY SEEDING YES [ ] NO [ ] (10\_PTS)
- POINTS AVAILABLE FOR QUESTION 4: (33\_PTS) \_\_\_\_\_
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [ ] NO [ ] (2\_PTS) (2\_PTS) \_\_\_\_\_
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [ ] NO [ ] (9\_PTS) (9\_PTS) \_\_\_\_\_
7. RECLAMATION:
- A. ROADWAY (1)\_ (2)\_ (3)\_ (PTS)
  - B. LOCATION (1)\_ (2)\_ (3)\_ (PTS)
  - C. PITS (1)\_ (2)\_ (3)\_ (PTS)
  - D. PIPELINES (1)\_ (2)\_ (3)\_ (PTS)
  - E. TANK DIKES (1)\_ (2)\_ (3)\_ (PTS)
  - F. API INSTALLED YES [ ] NO [ ] (3\_PTS)
  - G. ADEQUATE SEEDING MATERIALS (1)\_ (2)\_ (3)\_ (PTS)
  - H. WAS SEED BED ADEQUATE (1)\_ (2)\_ (3)\_ (PTS)
- POINTS AVAILABLE FOR QUESTION 7: (24\_PTS) \_\_\_\_\_

8. WAS RECLAMATION COMPLETED WITHIN:  
6 MTHS OF TD 6\_PTS ONLY; 4 MTHS OF TD 12\_PTS ONLY; 2 MTHS OF TD 19\_PTS ONLY;
- POINTS AVAILABLE FOR QUESTION 8: (19\_PTS) \_\_\_\_\_

TOTAL MAXIMUM POSSIBLE SCORE OF 99  
RECEIVED  
Office of Oil and Gas

TOTAL RECLAMATION SCORE: \_\_\_\_\_

6-9-16  
DATE RELEASED

JUN 15 2016

WV Department of  
Environmental Protection

[Signature]  
INSPECTOR'S SIGNATURE