9100426	

## WELL PLUGGING INSPECTION & RELEASE FORM

PLUG	GING COMMEN	ICED		OPERATOR	: ICG				
PLUGO	JING COMPLE AL PERMISSI	TED ON			ifford Sypolt				
A F.VDt	TO LEVATOO!	ON ON		METT NO:	CNGD 539				
1.	IS COAL B	EING MINED	IN THE AREA	?			$\mathtt{YES}_{\boldsymbol{X}}$	NO	N/A
2.	WERE CEMES		MIXED AND U	SED IN ACC	ORDANCE WITH	ACCEPT	TED IN	IDUSTR	Y
	Α.	BOTTOM HOI	LE PLUGGED				YESX	NO	N/A
	В.	100' PLUGS					YESX	NO	
	C.	LATEX PLUC	S USED FOR	H2S GAS			YES		N/Ax
	D.	PROPER PLU	JGS THROUGH	COAL SEAM			YESX	NO	N/A
	E.				ESHWATER		NO	N/A	
	F.	PROPER AMO	OUNT OF GEL	USED TO D	ISPLACE PLUGS	YESX	NO	N/A	
	TYPE		FROM		TO		PIPE	REMO	VED
		pugg	ed according	to mining re	eg				
	HW. Superior Landson			Technology (market market mark	New New York Control of the Control	-11 5			····
						_			
				*****		-::			
		***************************************							
_									
3.	WERE ALL	CHANGES APPI	ROVED BY IN	SPECTOR?				YESX	NO
4.					PROPERLY SIZ				
			50% OF THE	HEAVIEST S	TRING OF PIPE	EXPE(	CTED		
	TO BE PUL	LED?						YESX	NO
5.	DID THE O	PERATOR GIVE	THE INSPE	CTOR PROPE	R NOTICE?			YESX	NO
6.	WERE ACCU	RATE PLUGGI	IG RECORDS	KEPT BY TH	E OPERATOR?			YESX	NO
								11107	110
7.	WAS A PRO	PER MONUMENT	SET WITH	API NUMBER	ATTACHED?			YESX	NO
8.	DID WELL	SITE AND ACC	CESS ROAD M	EET THE FO	LLOWING RECLA	MATIO	J		
	REQUIREME:	NTS?							
	A. RECLA		YESX NO	B.				YESX	
	C. MULCH		YES X NO		PROPER DRAIN			YESX	
	E. SEEDE		YES X NO	F.	ALL EQUIPMEN	T REM	OVED	YESX	NO
	G. PIT B	ACKFILLED	YES x NO						
	3/11/21			Bryan	Harris				
	DATE REL	EASED	•	0	INSPECTOR'S S	IGNAT	JRE		***************************************

RECORD ALL VISITS TO THIS WELL ON PAGE 2