

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED 10-3-2016
 PLUGGING COMPLETED 10-18-2016
 VERBAL PERMISSION ON _____

OPERATOR: ICG TYGART VALLEY, LLC
 FARM: HAESSLY, W.J. & RITA
 WELL NO: CNGP 2248

1. IS COAL BEING MINED IN THE AREA? YES NO N/A
2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
 - A. BOTTOM HOLE PLUGGED YES NO N/A
 - B. 100' PLUGS YES NO N/A
 - C. LATEX PLUGS USED FOR H₂S GAS YES NO N/A
 - D. PROPER PLUGS THROUGH COAL SEAMS YES NO N/A
 - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES NO N/A
 - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A

TYPE	FROM	TO	PIPE REMOVED
EXPANDABLE CEMENT	4990'	3200'	1.5" TURBINE 4875'
"	3200'	860'	4.5" CASING 3200'
THIXOTROPIC CEMENT	860'	239'	MILLED 26.5' DP
EXPANDABLE CEMENT	239'	SURFACE	8 5/8" CASING FROM 454.5' TO 428'

3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NO
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES NO
5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NO
6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NO
8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?

A. RECLAIMED <input checked="" type="radio"/> YES NO	B. FENCES REPLACED <input checked="" type="radio"/> YES NO
C. MULCHED <input checked="" type="radio"/> YES NO	D. PROPER DRAINAGE <input checked="" type="radio"/> YES NO
E. SEEDED <input checked="" type="radio"/> YES NO	F. ALL EQUIPMENT REMOVED <input checked="" type="radio"/> YES NO
G. PIT BACKFILLED <input checked="" type="radio"/> YES NO	

8-25-17
DATE RELEASED

[Signature]
INSPECTOR'S SIGNATURE