



Lincoln? District, Wayne County, W. Va.

Elevation, 710'.

10" drive pipe, 36'; 8" casing, 292'; 6-5/8", 1232'.

	Top.	Bottom.
Quicksand and gravel	0	36
Sand	36	85
Slate	85	100
Sand and water	100	130
Black slate	130	160
P. slate	160	165
Lime	165	175
Sand	175	250
P. slate	250	260
Lime	260	270
Slate	270	350
B. slate	350	385
Lime	385	390
Coal	390	396
Lime	396	420
Rotten sand	420	445
Slate	445	460
Lime	460	470
Slate	470	500
Rotten sand	500	550
Slate	550	555
Lime	555	560
Slate	560	575
Sand and shell	575	590
Slate	590	670
Sand	670	740
Slate	740	765
Sand	765	785
B. slate	785	804
Salt Sand (show black oil)	804	910
Slate	910	960
Lime	960	975
Slate	975	990
Lime and shell	990	1005
Slate	1005	1025
H. sand and lime	1025	1045
Slate	1045	1060
H. sand and lime	1060	1160
Dark lime	1160	1210
Big Lime (100,000' gas at 1319')	1210	1390
Black slate and pebbles	1390	1400
Red rock	1400	1447
Injun Sand	1447	1459
Slate	1459	1525
Lime	1525	1540
Slate	1540	1941
Coffee shale	1941	1969
Sand, Berea (show of oil)	1969	1979
Lime shale	1979	2017
Sandy lime (show of oil)	2017	2035
Slate, to bottom	2035	2038 1/2