STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

Farm name:	POCAH	HONTAS LA	AND CO	MPANY ₍	Operato	r Well No	<u>POC</u>	A B-42	2	
LOCATION: Elevation: 1628'						Quadrangle: MULLEN				
LOOM TON	Dietrict:	SLAB FO	B FORK			/: <u>V</u>	YOMI	NG		
		15000'			-		Min	30	Sec	-
	Latitude	de: 4400'	Feet \	300011 01 <u></u>	31	eg. <u>- 2</u> 5	VIIII.	. 0	Sec.	
	Longitud	ie:	Feet	vvest of _		Deg. <u></u> -	IVIII	1	Sec.	
Well Type: 0	OIL	GASX_								
Company DIVERSIFIED PRODUCTION LLC. Coal Operator POCAHONTAS LAND COMPANY										
/		414 Summer Street or Owner								
	Charlesto	n WV 25301			•	BLUEFIEL	D, WV 24	701		
		,		Coal Op	erator	WYOMING	GEAGLE L	.LC		
Agent	JEFF M	1AST		or Owne	r	148 BRIS	TOL EAST	ROAD		
Permit Issu	ed Date	06/17/21			-	BRISTOL,	VA 24202		.,	
				Δξ	FIDAV	т				
STATE OF W	EST VIRG	SINIA,		<i>7</i> 11	IDAT	•				
County of JAC	KSON	ss:								
MELVIN MYE	RS	and	JAMES PU	JRSLEY		1	naina firet	duly s	worn accordin	g to law depose
					nd fillina	oil and ga	as wells ar	nd were a	employed by th	e above named
well operator	, and parti	cipated in the	work of pl	ugging an	d filling	the above	well say	that sa	aid work was	commenced on
									ollowing mann	
T) (DE		EDOM I			DIE	DE DEM	N/ED		I CC"	-
TYPE 16 SACKS C1A CEN		FROM 3010'	TC 2850				OF 1 1/2' TUBING		LEF"	1
30 SACKS C1A CEN		1650'	1550			212' OF 5 1/2" CASIN		2907' OF 5 1		'CASING
30 SACKS C1A CEN		1070'	810	-						
45 SACKS C1A CEN		550'	390						471' OF 8 5/8' C/	ASING CTS
104 SACKS C1A CEN	MENT	354'	SURFA	/CE					1-1-	
68 buil Both	سعدم جانسه	34.								
Description	of monum	_{ient:} 7" CSG W	'iTH API # 3	6" ABOVE (GROUND		a	and that	the work of plu	ugging and filling
said well was	completed	on the 15TH	_ day of _ ^{JU}	LY	/ 7	0.21				00 0
			-2/1	1/ ₁ /<	12	/// /				
And further	r deponent	s saith not.	110			Show		m	~~~~	Official Seal
									Notary	Public, State of West Virginia Kathryn Shafer
			The same		4 1			{ E		427 Charleston Road
Sworn and	subscribe	before me thi	s 14th d	ay of 10e	tobe	<u>er_</u> ,2	0 <u> 71</u> 0	\$ 1.//		Ripley WV 25271 mmission Expires May 9, 2024
		<u> </u>	. 1			North	- J	Land	My Gol	Hamman Musika
My commission	on expires:	5/4/2	4			Non	ary Public	nag		
				a.i	,,	INOIS	ary rubilo	,		۵
Affidavit revie	wed by the	Office of Oil	and Gas: 🕽	Huy)	Kevs	N	N	Title	E Tuspec	b:
			•	Y /		0			/	10/22/2021

WELL PLUGGING INSPECTION & RELEASE FORM

VERBAL PERMISSION ON WELL NO: 100 - 15-72 1. IS COAL BEING MINED IN THE AREA? 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H2S GAS C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGSTES NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGSTES NO N/A TYPE FROM TOP COMMAND CLASS A 3010' 2 \$50' 2775'./S Tubers COMMAND CLASS A 3010' 2 \$50' 2775'./S Tubers COMMAND CLASS A 3010' 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FRONCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED	VERBAL PERMISSION ON WELL NO: 100 - 100 N/A 1. IS COAL BEING MINED IN THE AREA? 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H25 GAS C. LATEX PLUGS USED FOR H25 GAS D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS STROUGH COAL SEAMS F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS (ES) NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS (ES) NO N/A TYPE FROM TO PIPE REMOVED COMENT Class A 30'0' 2850' 2775'.'S TOCKNO COMENT Class A 1650' 1550' 212'- 5.5 Casum Coment Class A 550' 330' COMENT Class A 550' 330' COMENT Class A 350' 500' COMENT CLASS A 350' COMENT CLASS A 350' 500' COMENT CLASS A 350' 500' COMENT CLASS A 350' 500' COMENT CLASS A 350' COMENT CLASS A 350' COMENT CLASS A 350' 500' COMENT CLASS A 350' 500' COMENT CLASS A 350' 500' COMENT CLASS A 350' COMEN		ING COMMENCED		OPERATOR: Oberstand from FARM: Possitional County	Lection		
1. IS COAL BEING MINED IN THE AREA? 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS SET TO PROTECT FRESHWATER E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGSUES NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGSUES NO N/A TYPE TYPE FROM TO PIPE REMOVED 2 850' COMUNT Class A 150'	1. IS COAL BEING MINED IN THE AREA? 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS STRINGUISH COAL SEAMS E. PROPER PLUGS STRINGUISH COAL SEAMS F. PROPER RAUGUS STO TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS CES NO N/A TYPE FROM TO PIPE REMOVED COMMITCINES A 1650' 1550' 2775' 1.5 Tuburg COMMITCINES A 1650' 1550' 1					<u> </u>		
2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS SET TO PROTECT FRESHWATER E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A TYPE FROM TO PIPE REMOVED 2575'-/.5 Tubum Communication Communic	2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS SET TO PROTECT FRESHWATER E. PROPER PLUGS SET TO PROTECT FRESHWATER E. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS VES NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS VES NO N/A TYPE FROM TO PIPE REMOVED COMMUNICIESS A 1650' 1550' 275'-1.5 Tabung COMMUNICIESS A 1650' 1550' 2775'-1.5 Tabung COMMUNICIESS A 1650' 1550' 2775'-1.5 Tabung COMMUNICIESS A 1650' 1550'				101 101 D 12	******		
STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H ₂ S GAS D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER RHOUNT OF GEL USED TO DISPLACE PLUGS FOR NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS FOR NO N/A TYPE FROM TO CAMBIS A 100' 1550' 1550' 2775'-1.5 Tabum Commun Class A 1010' 1550' 1550' 2775'-1.5 Tabum Commun Class A 1010' 1550'	STANDARDS? A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H2S GAS TES NO N/A D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS SET TO PROTECT FRESHWATER NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS TES NO N/A TYPE TYPE FROM TO PIPE REMOVED 2350' 2775'-1.5 Tabung Coment Class A 1010' Coment Class A 1020' 1030' 102' Coment Class A 102'	1.	IS COAL BEING	MINED IN THE AREA?		YES	NO	N/A
A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS THROUGH COAL SEAMS PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS FOR NO N/A TYPE FROM TO PIPE REMOVED Common Class A 1630' 2850' 2475'- /.5 Tubury Common Class A 1630' 1550' 2755' 272'- 5.5 Costum Common Class A 1630' 1550' 2755'- /.5 Tubury Common Class A 1630' 1550' 2775'- /.5 Tubury Common Class A 1630' 1630	A. BOTTOM HOLE PLUGGED B. 100' FLUGS C. LATEX PLUGS USED FOR H2S GAS C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS SET TO PROTECT FRESHWATER NO N/A F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS(ES) NO N/A TYPE FROM TO PIPE REMOVED Coment Class A 3010' 2350' 2375'-1.5 Tubure Coment Class A 3010' 3350' 3250' 3275'-1.5 Tubure Coment Class A 357' 3010'	2.		AND GEL MIXED AND US	ED IN ACCORDANCE WITH ACC	CEPTED I	NDUSTF	RΥ
C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS STATO PROTECT FRESHWATER E. PROPER PLUGS STAT TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS FES NO N/A TYPE FROM TO PIPE REMOVED 2975' /.5 Tuburg Communication Communication Communication Communication Communication Communication Communication Communication A S50' 380' Communication C	C. LATEX PLUGS USED FOR H2S GAS D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS (ES) NO N/A TYPE FROM TYPE FROM TO PIPE REMOVED 2950' 2975'-/.5 Tubur Comunit Class A 3010' Comunit Class A 1650' Comunit Class			TTOM HOLE PLUGGED		YES	NO	N/A
D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A TYPE FROM TO PIPE REMOVED Common Class A 1650' 1550' 2475'-1.5 Tuburg Common Class A 1650' 1550' 180' Common Class A 1650' 180' Common Class A 1650' 180' Common Class A 1650' 18	D. PROPER PLUGS THROUGH COAL SEAMS E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS (ES) NO N/A TYPE FROM TO PIPE REMOVED 2975'-/.5 Tubure Communicates A 1650' 1550' 212'-5.5 Casual Communicates A 1650' Surface 3.90' Communicates A 1650' Surface Comm		B. 10	0' PLUGS		(VES)	NO	_
E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS (ES) NO N/A TYPE FROM Communication Co	E. PROPER PLUGS SET TO PROTECT FRESHWATER F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS (ES NO N/A TYPE FROM TO PIPE REMOVED 2475'-/.5 Topice Communication Communicati							
TYPE FROM TO PIPE REMOVED Comment Class A 3010' 2850' 2975'-1.5 Tubus Comment Class A 1650' 1550' 212'-5.5 Cassur Class A 1650' 1550' 212'-5.5 Cassur Class A 550' 310' Comment Class A 550' 5m'macc 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	TYPE FROM TO PIPE REMOVED COMENT Class A 3010' 2850' 2975'- 1.5 Tubus Coment Class A 1650' 1550' 212'- 5.5 Casual Coment Class A 1650' 1550' 212'- 5.5 Casual Coment Class A 550' 370' 500' 500' 500' 500' 500' 500' 500' 5				The second secon	\ <u> </u>		N/A
TYPE FROM TO PIPE REMOVED COMMITCES A 3010' 2850' 2975'-1.5 Tubure CommitCes A 1650' 1550' 212'-5.5 Casum CommitCes A 1650' 310' 2850' 212'-5.5 Casum CommitCes A 550' 370' 200' 2015' A 550' 370' 200' 2015' A 359' 200' 2015' A 20	TYPE FROM TO PIPE REMOVED Centual Class A 3010' 2850' 2975'-1.5 Tubure Centual Class A 1650' 1550' 212'-5.5 Casture Centual Class A 1070' 510' Centual Class A 550' 330' Centual Class A 550' 300' Centual Class A 550' 300' Centual Class A 550' 500' 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO F. ALL EQUIPMENT REMOVED YES NO							
Cement Class A 3010' 2850' 2975'-1.5 Tubus Cement Class A 1650' 1550' 212'-5.5 Cassus Cement Class A 550' 310' Cement Class A 550' 370' Cement Class A 550' Surface 3. Were all changes approved by inspector? 4. Was the Equipment used for pulling casing properly sized and rigged to pull 150% of the heaviest string of pipe expected to BE pulled? 5. Did the Operator give the inspector proper notice? 6. Were accurate plugging records kept by the operator? 7. Was a proper monument set with api number attached? 8. Did well site and access road meet the following reclamation requirements? A. Reclaimed Yes No B. Fences replaced Yes No B. Fences replaced Yes No E. Seeded Yes No D. Proper drainage Yes No E. Seeded Yes No F. All Equipment removed Yes No E. Seeded Yes No F. All Equipment removed Yes No E. Seeded Yes No	Common Class A 1650' 1550' 212'- 5.5 Casing Common Class A 1650' 1550' 212'- 5.5 Casing Common Class A 1650' 310' 210' 212'- 5.5 Casing Common Class A 550' 370' 210' 210' 210' 210' 210' 210' 210' 21		F. PR	OPER AMOUNT OF GEL	USED TO DISPLACE PLUGS (YE	NO RE	N/A	
Common Class A 1650' 1550' 212'- 5.5 Casing Common Class A 550' 390' Common Class A 550' 390' Common Class A 550' 390' Common Class A 550' Surface 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	Commot Class A 1650' 1550' 212' - 5.5 Castury Commot Class A 550' 380' Commot Class A 550' 380' Commot Class A 550' Surface 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR FULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED RES	٠, ١						
Come of Class A 550' 370' Come of Class A 550' 500' Come of Class A 550'	Common Class A 550' 370' Common Class A 550' 500' Common Class A 550							
Come T Class A 359' Come T Class A 359' 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	Comunt Class A SSO' Surface 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO F. ALL EQUIPMENT REMOVED YES NO			1570			2.3 Ca	say.
3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO F. ALL EQUIPMENT REMOVED	Cancol School Plags 3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO							
3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO					 	· · · · · · · · · · · · · · · · · · ·	
3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO							
3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	3. WERE ALL CHANGES APPROVED BY INSPECTOR? 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	7637	· · · · · · · · · · · · · · · · · · ·	·				
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO	4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO	6660	1 between + lugs					
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO	4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO							
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO	4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO							
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO	4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO							*****
AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? NO DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? NO WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? NO WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? NO B. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO	3.	WERE ALL CHAN	IGES APPROVED BY INS	PECTOR?		ES	NO
TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO F. ALL EQUIPMENT REMOVED YES NO	TO BE PULLED? 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED C. MULCHED E. SEEDED YES NO D. PROPER DRAINAGE YES NO F. ALL EQUIPMENT REMOVED YES NO	4.	WAS THE EQUIF	MENT USED FOR PULLI	NG CASING PROPERLY SIZED			
5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE NO YES NO F. ALL EQUIPMENT REMOVED YES NO	5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE NO E. SEEDED					XPECTED	<i>a</i>	
6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO D. PROPER DRAINAGE NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED C. MULCHED E. SEEDED YES NO D. PROPER DRAINAGE NO F. ALL EQUIPMENT REMOVED YES NO		TO BE PULLED?	•			Æ5)	NO
6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO D. PROPER DRAINAGE NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED C. MULCHED E. SEEDED YES NO D. PROPER DRAINAGE NO F. ALL EQUIPMENT REMOVED YES NO	_					\rightarrow	
7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED NO F. ALL EQUIPMENT REMOVED YES NO	7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	5.	DID THE OPERA	TOR GIVE THE INSPEC	TOR PROPER NOTICE?		YES	NO
7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED NO F. ALL EQUIPMENT REMOVED YES NO	7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	6.	WERE ACCURATE	PLUGGING RECORDS K	EPT BY THE OPERATOR?		√E3	NΩ
8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS? A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	•	merch recording	THOUSERG RECORDS IN	arr br min ordinion.		-	110
REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	REQUIREMENTS? A. RECLAIMED C. MULCHED YES NO B. FENCES REPLACED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	7.	WAS A PROPER	MONUMENT SET WITH A	PI NUMBER ATTACHED?		ES)	NO
A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	A. RECLAIMED YES NO B. FENCES REPLACED YES NO C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	8.	DID WELL SITE	AND ACCESS ROAD ME	ET THE FOLLOWING RECLAMA	TION		
C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	C. MULCHED YES NO D. PROPER DRAINAGE YES NO E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO							
E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO	E. SEEDED YES NO F. ALL EQUIPMENT REMOVED YES NO			1 -1			1 - 1	
	i i i i i i i i i i i i i i i i i i i						YES	
G. PIT BACKPILLED MESA NO	10/18/21 LES NO Har Kause			l l	F. ALL EQUIPMENT	REMOVED	XES.	NO
1	10/18/21 Aug Kenersh		G. PIT BACKE	TITTED KES NO				
10/18/21 Aug Kareen			10/18/21		Huy Kanesala			
DATE RELEASED INSPECTOR & STENATURE	DATE RELEASED / INSPECTOR SIGNATURE		DATE RELEASE	<u> </u>	/ INSPECTOR 'S SIG	NATURE		

RECORD ALL VISITS TO THIS WELL ON PAGE 2