Form IR-11A

Rev. 8/21/2013

State of West Virginia
Office of Oil and Gas

INSPECTORS REPORT

Operator: KPI

API Number: 109-01463

Findings:

crew plugging well

Does this inspection identify any dust issues? ☐ Yes ☒ No. If Yes, explain.

Amy Kennedy
Oil & Gas Inspector

5/2/18
Date