STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

Farm name:	Heartwo	od Forest	and	_Operator We	ell No.:	PC-0	14A		
LOCATION:	Elevation	1,916.25		Quadrangle: Pineville					
		Baileysville	<u> </u>	_ County:	Wy	oming)	·	
	Latitude:	3,769	Feet South of	37 Deg.	35	Min.	00	Sec.	
	Longitud	e: <u>7,266</u>	Feet West of	81 Deg	20	Min.	00	Sec.	
Well Type:	OIL	GAS XXX							
Company	Ultra Prod	duction Comp	oany, LLC Coal O	perator Boo	ne East I	Developr	nent Co.		
	PO Box 28		ier			 -			
	Cedar Blu	ff, VA 24609	Cool						1 1 1 SAIR SIA (17-17-)
Agent	Andy H	rovatic	or Owr	-					
Permit Issu	ied Date								··········
Andy Hrovatic and say that well operato the 10th	they are exp	and	Mike Byrd ne work of plugging a work of plugging a , 2021, and the	and filling oil and filling the	and gas above w	wells ar vell say	nd were e that sa	worn according to employed by the a aid work was con oflowing manner:	above named mmenced on
		FROM	ТО					LEFT	
TYPE Cement		1058.9	0	PIPE REMOVED			7 inch 808 fee	rt	
said well wa	s completed er deponent ad subscribe	ts saith not.	day of October natheralis 274 day of (Number and Di 20 2		210	and that	the work of plugg	ing and filling for the second secon
		e Office of Oil	and Gas:	y Kermen	Notar	y Public	Title	e: Inspec	40/04/0004
			•	-					12/31/2021

API NO.: 47-109- 02585

WELL PLUGGING INSPECTION & RELEASE FORM

PLUG	GING COMMENC	ED 10/10/21	OPERATOR: Utra from FARM: Heavil Forces WELL NO: +-014A	رلسر					
PLUG	GING COMPLET	ED 10/22/21	FARM: HearTwood Forces	Havd					
VERB	AL PERMISSIC	N ON	WELL NO: 4C-0/9A						
1.	IS COAL BE	ING MINED IN THE ARE	A?	YES	NO	N/A			
2.	WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED IN								
	STANDARDS?	BOTTOM HOLE PLUGGED		ERS	ΝО	N/A			
		100' PLUGS		E		N/A			
		LATEX PLUGS USED FO	R H ₂ S GAS	YES		NID			
	D.	PROPER PLUGS THROUG	H CŌAL SEAMS	YES	NO	N/A			
	Ε.	PROPER PLUGS SET TO	PROTECT FRESHWATER ((ES) NO	N/A				
	F.	PROPER AMOUNT OF GE	L USED TO DISPLACE PLUGS (Es no	N/A				
. 1	TYPE	FROM	₹ °	PIPE	REMO	VED			
C/a	ss A Cemus	1058'	<u>Swface</u>						
				•					
					•				
з.	WERE ALL C	HANGES APPROVED BY I	NSPECTOR?		E	NO			
4.	WAS THE EO	UIPMENT USED FOR PUL	LING CASING PROPERLY SIZE	D					
			HEAVIEST STRING OF PIPE		20				
	TO BE PULL	ED?			ÆŠ	NO			
,- -			HAMAR READER NAMEANS		1	NO			
5.	DID THE OP	ERATOR GIVE THE INSP	ECTOR PROPER NOTICE?		مرت	NO			
6.	WERE ACCUR	ATE PLUGGING RECORDS	KEPT BY THE OPERATOR?		(ES	NO			
					\sim				
7.	WAS A PROP	ER MONUMENT SET WITH	API NUMBER ATTACHED?		ES	NO			
8.	DID WELL S	ITE AND ACCESS ROAD	MEET THE FOLLOWING RECLAM	ATION	1				
	REQUIREMEN				1				
	A. RECLAI	MED YES NO	B. FENCES REPLAC	ED	YE	NO			
	C. MULCHE	D (YES) NO	D. PROPER DRAINA	AGE	YES	NO			
	E. SEEDED	1 /	F. ALL EQUIPMENT	REMOVED	YES	NO			
	G. PIT BA	CKFILLED YES NO		4					
	17/28/21	Ŭ	N. W.	~ .					
	DATE RELE	ASED	INSPECTOR'S SI	GNATURE					

RECORD ALL VISITS TO THIS WELL ON PAGE 2